



Tree Safety inspection

Oakleaf Place
Hursley Road, Chandlers Ford
SO53 2RL

Survey date: 2nd December 2024.

Prepared by Chris Anderson: TecArborA.

Contents

Survey reference: First Port: **OP02122024**

Contents:

- 1.0: Introduction
- 1.1: Scope
- 1.2: Target risk
- 1.3: Overview
- 1.4: Synopsis
- 1.5: Contractor and legal requirements
- 1.6: Disclaimer
- 1.7: Map
- 1.8: General tree assessment (detailed)
- 1.9: Tree Survey Work Analysis
- 1.10: Reinspection dates.

1.0 Introduction:

I am Chris Anderson, and I bring 25 years of expertise in the arboricultural industry. I am a qualified Professional Tree Inspector and a technician member of the Arboricultural Association. Additionally, I hold a NEBOSH certificate. This report confidently integrates essential health and safety considerations.

Reference materials used within this survey from Principles of Tree Hazard Assessment (Dr David Longsdale) -The Body Language of Trees (Claus Mattheck and Helge Breloer), Diagnosis of Ill Health Trees (R.G Strouts and T.G Winter)

1.1 Scope:

Jack Hildebrandt from JH Tree Services has instructed me to conduct a visual tree inspection on all stand-alone trees and a negative inspection on all others within Kensington fields and report all findings.

- All stand-alone trees will be identified as a new numbered silver tag attached at breast height.
- All trees on site are to be visually inspected by looking at the available tree attributes and is only a visual inspection.
- Trees will be inspected, and detailed findings will be added to tree survey data, along with all work recommendations, times scales and following inspection dates.

1.2 Target risk:

The area around a tree where the whole tree or parts of the tree may fail and come into contact with people or property from naturally occurring events or poor management. If there isn't anybody or structures in the target zone, there is no risk of injury or damage when the tree falls. The more people in the target zone, the greater the risk of people/property being hit by a falling limb or a whole tree. Target zones around trees can be classified as follows:

- **Low-risk target zone:** Places seldom frequented or near any property.
- **Medium-risk target zone:** Places visited occasionally, have a low population density, or are near the property.
- **High-risk target zone:** Places where people can be expected most of the time or at some times, e.g., assembly areas, footpaths, tracks, desired lines, roads, car parks, work/activity areas, any other building/structure, or any place that is frequented by people including buildings/structures in frequent use. Due to how premises are used, target zone assignment should be reviewed, and changes should be made if the risks change.

The person who controls the land or premises or occupies it must show a duty of care towards anyone entering the land in relation to the dangers presented due to the state of the land or premises. In short, all care must be taken, as is reasonable,

to ensure third parties will not suffer injury or damage. This might include erecting warning signs to alert anyone to possible danger or perceived risk. This is known as Occupiers' Liability. All works recommended within this report must be carried out due to the above act.

1.3 Overview:

A visual inspection was conducted on 22 young to semi-mature trees located within the grounds of Oakleaf Place. Three trees along the southern boundary were recently removed, and eco plugs were inserted into two of these stumps to stop regeneration.

All trees within the survey's scope have been assigned a unique identification number displayed on a silver tag affixed approximately 1.5 meters above the ground on each trunk. This identification number corresponds to the mapped trees in the accompanying survey documentation. The recorded locations of the trees are accurate to within one meter of their actual positions on site.

In consideration of health and safety standards and the ongoing development of the trees, all findings and recommendations outlined in this survey must be reasonably adhered to within the designated timeframe on the survey comments.

My professional assessment is that the trees inspected fall within the medium category target zone due to their size, condition, location, and frequency of people.

All the trees inspected have been well maintained according to British standards BS3998. Other trees require general maintenance for good tree management.

1.4 Synopsis:

- All trees surveyed are not within a conservation area; however, T8: Lime is protected with a Tree preservation order (TPO) from the information I have received.
- All the trees have been surveyed and are in normal condition based on age and location.
- Trees T1, T3, T4, T7, T6, T8, T11, T18, T20, and T21 require work, and recommendations are found on Page 1.9, Tree survey work analysis.
- T6: Norway maple and T8; Lime requires re-pollarding. I have advised this due to the overall condition of both trees.
- Trees T20 and T21 require removal to ground level. Tree T20 exhibits a fungal infection at and around the base of the trunk, accompanied by weeping sap that has turned brown. This condition indicates a likelihood of failure at this point. Tree T21, in contrast, possesses a loose and defective root system that will inevitably result in the tree's failure.
- T4 is equipped with a low-voltage aerial-bound conductor (LV: ABC-240 volts) that traverses its vicinity. Due to the proximity of the aerial bundled conductor (ABC), only contractors qualified in utility arboriculture are permitted to work on this tree.

- I have formally reported the third-party Ash tree located on the western boundary to Hampshire Highways' tree department as it is their responsibility due to the concerns regarding its overall condition. I have been informed that the highways department has conducted an inspection of this tree, and it has now been recorded in their system.

1.5 Contractor and legal requirements:

Suitably qualified, insured, and experienced contractors must conduct tree works and should conform to guidelines set out in British Standard 3998; however, we can professionally advise on recommendations for contractors.

Trees covered by Tree Preservation Orders or within a Conservation Area require permission or consent from your Local Planning Authority (LPA). It is necessary to gain confirmation from the LPA of any TPOs or CAs on the site and to follow the necessary application procedure if tree surgery or felling is required for protected trees. Full planning consent will, however, override the need for a separate application, providing that details of all tree works were included in the submission and subsequently approved by the local authority.

You do not need consent from the local LPA if you remove Dead Wood, but I always advise you to inform the local LPA out of courtesy and professionalism.

Under normal circumstances, it is a criminal offence to disturb or destroy - intentional or unintentional - the nesting sites of wild birds or the roost sites of bats under the 'Wildlife & Countryside Act 1981 and the 'Countryside and Rights of Way Act 2000'. There was no visual activity of any bat roost or nesting birds, but this does not indicate a non-presence at the time of this survey.

Therefore, avoid carrying out significant tree work during the bird nesting season (mid-March to the end of July) and ensure that trees are professionally surveyed for signs of bat roosts and bat activity before starting any tree work. However, all trees have the potential to be bat habitats and are not always easy to spot.

1.6 Disclaimer:

The trees referred to in this report are living entities and, therefore, are subject to natural processes. They will also be subject to environmental changes caused by human activities and weather conditions. The inspection relies on visual attributes of tree health and structure (body language of trees by David Lonsdale), which can be assessed from a ground-based inspection. Hidden defects which are not readily visible may not be detected. Therefore, I cannot wholly guarantee the condition and safety of the trees inspected beyond what can be reasonably assessed from the procedure.

This report is valid for one year from the date of receipt.


END OF REPORT.



Chris Anderson, TechArborA

8th December 2024

1.7: MAP



© Crown copyright and database rights 2024. Ordnance Survey AC0000822731.

1.8: General tree assessment (detailed)

First Port:OP
Oak leaf place
Hursley Road
Southampton
Hampshire
SO532RL

Anson Arboriculture

Drivetts Cottage
Purbrook Heath Road
Purbrook
Hampshire
PO75RZ

Phone: 07557878872
Mobile: N/A
ansonarb@hotmail.com

General Tree Assessment (Detailed)

Oak leaf Place

Tree ID: 1 Common Yew
Taxus baccata **Tag:** 742 **Assessor:** Chris Anderson
TPO: **Date:** 02-Dec-24
Tree Comment:
Survey Comment: This tree has historical dead pegs on the lower trunk area, these require removing. There are rubbing branches throughout the crown. The crown has been reduced down by a couple of meters. A small amount of light deadwood throughout.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	5 m	2 m	1	1150 mm	Semi-mature			N/A	02-Dec-27	Good
Observations	Root	Stem		Branch		Leaf/Bud				
	No visual defects	Old pruning wounds Stubs Tight union		No visual defects		Normal				
Work	Category	Action		Priority		Done				
	See Comment	Unspecified		6 Months		No				

Tree ID: 2 Common Yew
Taxus baccata **Tag:** 825 **Assessor:** Chris Anderson
TPO: **Date:** 02-Dec-24
Tree Comment:
Survey Comment: This tree has had a 2 meter reduction in height, the lower trunk area has two co-dominant stems along with some minor dead wood throughout the crown.

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	5 m	3 m	1	950 mm	Semi-mature			N/A	02-Dec-27	Good
Observations	Root	Stem		Branch		Leaf/Bud				
	No visual defects	Stubs		Tight union		Normal				
Work	Category	Action		Priority		Done				
	No action	Unspecified				No				

General Tree Assessment (Detailed)

Tree ID: 3	Common Yew <i>Taxus baccata</i>					Tag: 826		Assessor: Chris Anderson		
						TPO:		Date: 02-Dec-24		
						Tree Comment:				
						Survey Comment: The tree is being suppressed by neighbouring trees forcing the crown to grow to the north west. A small stem on the west rubbing on the fence requires removing.				
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	5 m	3 m	1	490 mm	Young			N/A	02-Dec-27	Fair
Observations	Root			Stem		Branch			Leaf/Bud	
	No visual defects			Bifurcated					Normal	
Work	Category			Action					Priority	Done
	Prune			From buildings/structure/tree					6 Months	No

Tree ID: 4		Unknown --			Tag: 827 TPO:		Assessor: Chris Anderson Date: 02-Dec-24				
		Tree Comment:									
		Survey Comment: This tree is growing towards the road and appears to be in decline, the crown is looking sparse with dead wood present. Dead wood requires removing, there is an LV ABC conductor running through this tree. I recommend a reinspection early summer to evaluate leaf throw, this will give a good indication of this trees health.									
Details		Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
		7 m		1	1300 mm	Semi-mature			N/A	02-Dec-25	Fair
Observations		Root			Stem		Branch		Leaf/Bud		
		No visual defects			No visual defect		Apical die back		25% dead / absent		
Work		Category			Action					Priority	Done
		Remove			Major dead wood					3 Months	No

General Tree Assessment (Detailed)

Tree ID: 5	Common Yew <i>Taxus baccata</i>					Tag: 828 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
	Tree Comment:									
	Survey Comment: This tree is suppressed by neighbouring trees forcing crown growth towards the south, small branches resting of fence.									
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	6 m	2 m	1	600 mm	Young			N/A	02-Dec-27	Fair
Observations	Root			Stem		Branch		Leaf/Bud		
	No visual defects			No visual defect		Old pruning wounds Stubs		Normal		
Work	Category			Action		Priority				Done
	No action			Unspecified						No

Tree ID: 6	Norway Maple <i>Acer platanoides</i>					Tag: 829 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
	Tree Comment:									
	Survey Comment: This tree has been pollarded twice over the years reproducing a leggy crown dominately over the south parking area of a neighbouring property. One of the old pollard points has failed at 4 meters on the south side, Recommend reducing the crown by 3 meters to reduce wind loading and the reduce the whip lash effect from the wind.									
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	15 m	5 m	1	1600 mm	Semi-mature			N/A	02-Dec-26	Fair
Observations	Root			Stem		Branch		Leaf/Bud		
	No visual defects			No visual defect		Old pruning wounds Cavities Pollard		Normal		
Work	Category			Action		Priority				Done
	Reduce crown(s)			By specified percentage (see comment)		6 Months				No

General Tree Assessment (Detailed)

Tree ID: 7	Lawson Cypress <i>Chamaecyparis lawsoniana</i>					Tag: 830 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
	Tree Comment:					Survey Comment: This tree is leaning significantly towards the northwest, a recent large branch has been removed at 2.2 meters on the north side. Recommend removing dead pegs to above head height due to them being in eye line				
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	6 m	1 m	1	600 mm	Young			N/A	02-Dec-27	Fair
Observations	Root			Stem		Branch			Leaf/Bud	
	No visual defects			Leaning		Old pruning wounds			Normal	
Work	Category			Action					Priority	Done
	Remove			Remove Deadwood					6 Months	No

Tree ID: 8	Common Lime <i>Tilia europaea</i>					Tag: 831 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
	Tree Comment:					Survey Comment: This tree has been pollarded on a number of occasions over the years, producing a new crown, there are significant rubbing branches and tight unions throughout. Unable to determine DBH due to basil area epecirmic growth, this also impeded a thorough inspection of the lower trunk area, recommend removing this and respect this area and to repollard this tree for managmet resions.				
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	18 m	3 m	2		Mature			N/A	02-Dec-25	Fair
Observations	Root			Stem		Branch			Leaf/Bud	
	No visual defects			Old pruning wounds Bifurcated Multi stemmed Tight union		Old pruning wounds Pollard Tight union			Normal	
Work	Category			Action					Priority	Done
	Pollard			Pollard to 5 m					1 year	No
	See Comment			Unspecified						No

General Tree Assessment (Detailed)

Tree ID: 9	Common Yew <i>Taxus baccata</i>					Tag: 832 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
	Tree Comment:									
	Survey Comment: This tree has had the height reduction of 2 meters, this yew has been pruned to form a good green screen giving the appearance of a hedge.									
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	3 m	1 m	1	550 mm	Young			N/A	02-Dec-27	Fair
Observations	Root			Stem		Branch		Leaf/Bud		
	No visual defects			Old pruning wounds		No visual defects		Normal		
Work	Category			Action				Priority		Done
	No action			Unspecified						No

Tree ID: 10	Lawson Cypress <i>Chamaecyparis lawsoniana</i>					Tag: 833 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
	Tree Comment:									
	Survey Comment: This tree has been suppressed by the neighbouring pine tree that has been removed in the past few weeks.									
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	11 m	2 m	1	768 mm	Semi-mature			N/A	02-Dec-27	Fair
Observations	Root			Stem		Branch			Leaf/Bud	
	No visual defects			Old pruning wounds		No visual defects Old pruning wounds			Normal	
Work	Category			Action					Priority	
	No action			Unspecified					Done No	

General Tree Assessment (Detailed)

Tree ID: 11	Sycamore <i>Acer pseudoplatanus</i>	Tag: 834 TPO:	Assessor: Chris Anderson Date: 02-Dec-24
Tree Comment:			
Survey Comment: This tree has had historical crown works that have adapted well, The lower trunk has a tight co-dominant stem at 1 meter, this is of no concern at this time. The tree requires a light reduction on the northwest side away from the building.			

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	16 m	4 m	1	1680 mm	Semi-mature			N/A	02-Dec-27	Good
Observations	Root			Stem		Branch			Leaf/Bud	
	No visual defects			Bifurcated Tight union		Old pruning wounds			Normal	
Work	Category			Action					Priority	Done
	Prune			From buildings/structure/tree by 1.0m					6 Months	No

Tree ID: 12	Leyland Cypress <i>X Cupressocyparis leylandii</i>	Tag: 835 TPO:	Assessor: Chris Anderson Date: 02-Dec-24
Tree Comment:			
Survey Comment: This tree is being suppressed by neighbouring trees. There is a wooden frames with flower pots attached on the north side at 1 meter.			

Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	4 m	2 m	1	22 mm	Young			N/A	02-Dec-27	Fair
Observations	Root			Stem		Branch			Leaf/Bud	
	No visual defects			No visual defect		Minor dead wood			Normal	
Work	Category			Action					Priority	Done
	No action			Unspecified						No

General Tree Assessment (Detailed)

Tree ID: 13	Sycamore <i>Acer pseudoplatanus</i>					Tag: 836 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
	Tree Comment:									
	Survey Comment: This tree has twin stems from the ground level along with a historical crown reduction									
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	15 m	5 m	2	890 mm	Semi-mature			N/A	02-Dec-27	Fair
Observations	Root			Stem		Branch			Leaf/Bud	
	No visual defects			Multi stemmed		Minor dead wood Old pruning wounds			Normal	
Work	Category			Action					Priority	Done
	No action			Unspecified						No

Tree ID: 14	Prunus <i>Prunus Spp.</i>					Tag: 837 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
	Tree Comment:									
	Survey Comment: This tree is being suppressed by neighbouring trees from the south, causing the tree to grow north. The center spire has been historically removed, the crown has redeveloped well around this area.									
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	14 m	5 m	1	700 mm	Semi-mature			N/A	02-Dec-27	Fair
Observations	Root			Stem		Branch			Leaf/Bud	
	No visual defects			Leaning Old pruning wounds		Old pruning wounds			Normal	
Work	Category			Action					Priority	Done
	No action			Unspecified						No

General Tree Assessment (Detailed)

Tree ID: 15		Whitebeam <i>Sorbus aria</i>				Tag: 838 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
		Tree Comment:				Survey Comment: This tree has historical pruning wounds around the trunk area.				
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	5 m	3 m	1	500 mm	Young			N/A	02-Dec-27	Good
Observations	Root		Stem		Branch		Leaf/Bud			
	No visual defects		Old pruning wounds		No visual defects		Normal			
Work	Category		Action				Priority		Done	
	No action		Unspecified						No	

Tree ID: 16		Norway Maple <i>Acer platanoides</i>				Tag: 839 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
		Tree Comment:				Survey Comment: This tree has a small amount of effluent running out of the union area at 1.5 meters on the south side with two large dead pegs above. The tight union has developed extra wood on the south, this is of no concern currently.				
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	10 m	4 m	1	1320 mm	Semi-mature			N/A	02-Dec-27	Good
Observations	Root		Stem		Branch		Leaf/Bud			
	No visual defects		Old pruning wounds Stubs Bifurcated Tight union		No visual defects		Normal			
Work	Category		Action				Priority		Done	
	Remove		Major dead wood				6 Months		No	

General Tree Assessment (Detailed)

Tree ID: 17		Common Lime <i>Tilia europaea</i>				Tag: 840 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
		Tree Comment:								
		Survey Comment: This tree is being suppressed by neighbouring trees, not a good specimen.								
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	4 m	2 m	1	220 mm	Young			N/A	02-Dec-26	Fair
Observations	Root			Stem		Branch			Leaf/Bud	
	No visual defects			Old pruning wounds		No visual defects Old pruning wounds			Normal	
Work	Category			Action					Priority	Done
	No action			Unspecified						No

Tree ID: 18		Common Hornbeam <i>Carpinus betulus</i>				Tag: 841 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
		Tree Comment:								
		Survey Comment: This tree requires branches growing west over the parking bay to be reduced so as not to impact parking vehicles. The poor pruning on this side requires to be correctly done as there are pegs on what is a nice tree.								
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	8 m	4 m	1	700 mm	Semi-mature			N/A	02-Dec-27	Good
Observations	Root			Stem		Branch			Leaf/Bud	
	No visual defects			No visual defect		No visual defects			Normal	
Work	Category			Action					Priority	Done
	Raise low canopy			To 3.0m					6 Months	No

General Tree Assessment (Detailed)

Tree ID: 19		Silver Birch <i>Betula pendula</i>				Tag: 842 TPO:				Assessor: Chris Anderson Date: 02-Dec-24	
Tree Comment:											
Survey Comment: No comment.											
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition	
	15 m	4 m	1	800 mm	Semi-mature			N/A	02-Dec-27	Good	
Observations	Root			Stem		Branch			Leaf/Bud		
	No visual defects			No visual defect		No visual defects			Normal		
Work	Category			Action					Priority		Done
	No action			Unspecified							No

Tree ID: 20		Silver Birch <i>Betula pendula</i>				Tag: 843 TPO:				Assessor: Chris Anderson Date: 02-Dec-24	
Tree Comment:											
Survey Comment: This tree was planted too shallow, this can be seen by the high root flare and exposed roots above ground level. The north side of the lower trunk has fungal infection , this can be associated with Armillaria species. This tree will eventually fail at this area.											
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition	
	11 m	3 m	1	500 mm	Semi-mature			N/A	02-Mar-26	Fair	
Observations	Root			Stem		Branch			Leaf/Bud		
	Fungus or decay Soil erosion			Stress marks / slime flux		Old pruning wounds Cavities			Normal		
Work	Category			Action					Priority		Done
	Fell			Fell and remove stump(s)					3 Months		No

General Tree Assessment (Detailed)

Tree ID: 21	Whitebeam <i>Sorbus aria</i>					Tag: 844 TPO:		Assessor: Chris Anderson Date: 02-Dec-24		
	Tree Comment:									
	Survey Comment: This tree is in a dangerous condition, on pushing the stem it is clear that there is excessive movement below ground level, indicating root death/failure. This must be a priority to remove.									
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition
	6 m	2 m	1	300 mm	Young			N/A	02-Mar-26	Dangerous
Observations	Root			Stem		Branch			Leaf/Bud	
	Fungus or decay			Fungus or decay		No visual defects			Normal	
	Soil erosion			Bark wounds						
	Damage to buttress roots									
Work	Category			Action					Priority	Done
	Fell			Fell and remove stump(s)					Critical	No

Tree ID: 22	Goat Willow <i>Salix caprea</i>					Tag: 845 TPO:		Assessor: Chris Anderson Date: 02-Dec-24			
	Tree Comment:										
	Survey Comment: This tree is a small feature for residents with various garden ornaments around the base along with hanging features.										
Details	Height	Spread	Stems	Ø	Maturity	Bat	Con Area	Prev Insp	Next Due	Condition	
	3.5 m	1 m	2	250 mm	Young			N/A	02-Dec-27	Fair	
Observations	Root			Stem		Branch			Leaf/Bud		
	No visual defects			Old pruning wounds		Minor dead wood Old pruning wounds			Normal		
Work	Category			Action					Priority		Done
	No action			Unspecified							No

Tree Survey Action Analysis

Tree: 4

TagNo: 827

Unknown

--

Tree Comment:

Survey Comment: This tree is growing towards the road and appears to be in decline, the crown is looking sparse with dead wood present. Dead wood requires removing, there is an LV ABC conductor running through this tree. I recommend a reinspection early summer to evaluate leaf throw, this will give a good indication of this trees health.

Action Recommendations:

Done

Priority

Remove

Major dead wood

No

3 Months

Tree: 5

TagNo: 828

Common Yew

Taxus baccata

Tree Comment:

Survey Comment: This tree is suppressed by neighbouring trees forcing crown growth towards the south, small branches resting of fence.

Action Recommendations:

Done

Priority

No action

Unspecified

No

Tree: 6

TagNo: 829

Norway Maple

Acer platanoides

Tree Comment:

Survey Comment: This tree has been pollarded twice over the years reproducing a leggy crown dominately over the south parking area of a neighbouring property. One of the old pollard points has failed at 4 meters on the southg side, Recommend reducing the crown by 3 meters to reduce wind loading and the reduce the whip lash effect from the wind.

Action Recommendations:

Done

Priority

Reduce crown(s)

By specified percentage (see comment)

No

6 Months

Tree: 7

TagNo: 830

Lawson Cypress

Chamaecyparis lawsoniana

Tree Comment:

Survey Comment: This tree is leaning significantly towards the northwest, a recent large branch has been removed at 2.2 meters on the north side. Recommend removing dead pegs to above head height due to them being in eye line

Action Recommendations:

Done

Priority

Remove

Remove Deadwood

No

6 Months

Tree Survey Action Analysis				
Tree: 8				
TagNo: 831	Action Recommendations:			Done Priority
Common Lime	Pollard	Pollard to 5 m	No	1 year
<i>Tilia europaea</i>	See Comment	Unspecified	No	
Tree Comment:				
Survey Comment: This tree has been pollarded on a number of occasions over the years, producing a new crown, there are significant rubbing branches and tight unions throughout. Unable to determine DBH due to basal area epicormic growth, this also impeded a thorough inspection of the lower trunk area, recommend removing this and respect this area and to repollard this tree for management reasons.				
Tree: 9				
TagNo: 832	Action Recommendations:			Done Priority
Common Yew	No action	Unspecified	No	
<i>Taxus baccata</i>				
Tree Comment:				
Survey Comment: This tree has had the height reduction of 2 meters, this yew has been pruned to form a good green screen giving the appearance of a hedge.				
Tree: 10				
TagNo: 833	Action Recommendations:			Done Priority
Lawson Cypress	No action	Unspecified	No	
<i>Chamaecyparis lawsoniana</i>				
Tree Comment:				
Survey Comment: This tree has been suppressed by the neighbouring pine tree that has been removed in the past few weeks.				

Tree Survey Action Analysis			
Tree: 11			
TagNo: 834	Action Recommendations:		Done Priority
Sycamore <i>Acer pseudoplatanus</i>	Prune	From buildings/structure/tree by 1.0m	No 6 Months
Tree Comment: Survey Comment: This tree has had historical crown works that have adapted well, The lower trunk has a tight co-dominant stem at 1 meter, this is of no concern at this time. The tree requires a light reduction on the northwest side away from the building.			
Tree: 12			
TagNo: 835	Action Recommendations:		Done Priority
Leyland Cypress <i>X Cupressocyparis leylandii</i>	No action	Unspecified	No
Tree Comment: Survey Comment: This tree is being suppressed by neighbouring trees. There is a wooden frames with flower pots attached on the north side at 1 meter.			
Tree: 13			
TagNo: 836	Action Recommendations:		Done Priority
Sycamore <i>Acer pseudoplatanus</i>	No action	Unspecified	No
Tree Comment: Survey Comment: This tree has twin stems from the ground level along with a historical crown reduction			
Tree: 14			
TagNo: 837	Action Recommendations:		Done Priority
Prunus <i>Prunus Spp.</i>	No action	Unspecified	No
Tree Comment: Survey Comment: This tree is being suppressed by neighbouring trees from the south, causing the tree to grow north. The center spire has been historically removed, the crown has redeveloped well around this area.			

Tree Survey Action Analysis				
Tree: 15				
TagNo: 838	Action Recommendations:			Done Priority
Whitebeam <i>Sorbus aria</i>	No action	Unspecified	No	
Tree Comment: Survey Comment: This tree has historical pruning wounds around the trunk area.				
Tree: 16				
TagNo: 839	Action Recommendations:			Done Priority
Norway Maple <i>Acer platanoides</i>	Remove	Major dead wood	No	6 Months
Tree Comment: Survey Comment: This tree has a small amount of effluent running out of the union area at 1.5 meters on the south side with two large dead pegs above. The tight union has developed extra wood on the south, this is of no concern currently.				
Tree: 17				
TagNo: 840	Action Recommendations:			Done Priority
Common Lime <i>Tilia europaea</i>	No action	Unspecified	No	
Tree Comment: Survey Comment: This tree is being suppressed by neighbouring trees, not a good specimen.				
Tree: 18				
TagNo: 841	Action Recommendations:			Done Priority
Common Hornbeam <i>Carpinus betulus</i>	Raise low canopy	To 3.0m	No	6 Months
Tree Comment: Survey Comment: This tree requires branches growing west over the parking bay to be reduced so as not to impact parking vehicles. The poor pruning on this side requires to be correctly done as there are pegs on what is a nice tree.				

Tree Survey Action Analysis				
Tree: 19				
TagNo: 842	Action Recommendations:			Done Priority
Silver Birch <i>Betula pendula</i>	No action	Unspecified	No	
Tree Comment: Survey Comment: No comment.				
Tree: 20				
TagNo: 843	Action Recommendations:			Done Priority
Silver Birch <i>Betula pendula</i>	Fell	Fell and remove stump(s)	No	3 Months
Tree Comment: Survey Comment: This tree was planted too shallow, this can be seen by the high root flare and exposed roots above ground level. The north side of the lower trunk has fungal infection , this can be associated with Armillaria species. This tree will eventually fail at this area.				
Tree: 21				
TagNo: 844	Action Recommendations:			Done Priority
Whitebeam <i>Sorbus aria</i>	Fell	Fell and remove stump(s)	No	Critical
Tree Comment: Survey Comment: This tree is in a dangerous condition, on pushing the stem it is clear that there is excessive movement below ground level, indicating root death/failure. This must be a priority to remove.				
Tree: 22				
TagNo: 845	Action Recommendations:			Done Priority
Goat Willow <i>Salix caprea</i>	No action	Unspecified	No	
Tree Comment: Survey Comment: This tree is a small feature for residents with various garden ornaments around the base along with hanging features.				

1.10: Reinspection dates

It is recommended that all trees be reinspected in November 2026, two years from the survey date.