HAZARD SAFETY AUDIT

Bursledon Parish Council

Site: Long Lane Recreation Ground, Bursledon

Chesil House, Arrow Close,
Boyatt Wood,Hampshire, SO50 4SY
Tel: 023 8098 6229 www: info@cbatrees.co.uk

www: cbatrees.co.uk
The Complete Arboricultural Consultancy

September 2024
CBA11083LLRG v5

HAZARD SURVEY AUDIT NOTES

This Hazard Survey Audit has been undertaken in consideration of current good arboricultural practice with regards to the health and safety of the tree stock on this site.

Inspection Method

This survey is a basic data collection exercise undertaken from ground level only, and records tree condition at the time of survey. This will identify any visible signs of ill-health or major defects, advising further detailed investigation where appropriate. No assessment has been carried out in respect of ingress of roots into underground services or the potential of indirect property damage. Such matters are beyond the scope of this survey.

- Each tree has been numbered and, where instructed, for future identification on site, tagged using small durable metal or plastic tags.

- An assessment of a tree's **age classification** is made in terms of its maturity within the site's landscape and recorded thus:

Y	**=**	**young trees i.e. newly planted or just established**
SM	**=**	**semi-mature trees, i.e. those that have reached one-third of their anticipated life expectancy**
EM	**=**	**early-mature trees, i.e. those that have reached two-thirds of their anticipated life expectancy**
M	**=**	**mature trees, i.e. those that have entered the final third of their anticipated life expectancy**
OM	**=**	**over-mature trees, as above but showing signs of low vigour and decline**
V	**=**	**veteran, trees that achieved their full life expectancy, are of exceptional size/age and of conservation value**

- The **trees height** is recorded in 5 metre (m) increments: -

<5	**=**	**under 5 metres in height**
5-10	**=**	**between 5 and 10 metres in height**
10-15	**=**	**between 10 and 15 metres in height**
15-20	**=**	**between 15 and 20 metres in height**
>20	**=**	**over 20 metres in height**

- The **trunk diameter** is recorded in 150 millimetre (mm) increments, taken at 1.5 metres above ground level on single stem trees and just above the root flair on multi-stemmed trees:-

<150	**=**	**under 150 millimetres diameter**
150-300	**=**	**between 150 and 300 millimetres diameter**
300-450	**=**	**between 300 and 450 millimetres diameter**
450-600	**=**	**between 450 and 600 millimetres diameter**
>600	**=**	**over 600 millimetres diameter**

- The **crown spread** is recorded in 5 metre (m) increments and is an average overall crown spread taken from drip line to drip line

<5	**=**	**under 5 metres crown spread**
5-10	**=**	**between 5 and 10 metres crown spread**
10-15	**=**	**between 10 and 15 metres crown spread**
15-20	**=**	**between 15 and 20 metres crown spread**
>20	**=**	**over 20 metres crown spread**

- An assessment of a tree's structural and physiological **overall condition** is to be made as:

Good	**=**	**none or limited structural defects and good physiological condition**
Fair	**=**	**remediable structural defects and/or below average physiological condition**
Poor	**=**	**irremediable structural defects and/or poor physiological condition**
Dead	**=**	**moribund, no further useful life**

- It is strongly recommended that tree works should be undertaken within the timescales denoted in the Priorities column, and are recorded as action required:

Imminently dangerous	**=**	**Immediate**
Urgent	**=**	**Within 1 month**
Necessary	**=**	**Within 3 months**
Important	**=**	**Within 6 months**
Routine	**=**	**Within 12 months**

- Where ivy is identified on a tree, to prevent the tree from becoming suppressed, to reduce the risk of wind-throw and to alleviate additional weight, it has been recommended that a 300mm section of the ivy should be severed and removed around the base of the tree, unless otherwise stated.

- At the time of inspection, due to ivy cover, location etc, it may not be possible to verify the health and safety of the trees and it is therefore essential that re-inspections be undertaken within the recommended timescales to reduce the risk of potential hazard.

- Comments have been provided only where considered appropriate or necessary to provide additional information.

- Any tree groups have been assessed using estimated and representative data only.

- All dimensions recorded have been estimated and are given for guidance purposes only.

- The data collected and any advice provided within this report is supplied in the interests of sound arboricultural management. Trees are a living dynamic organism that can be affected by external conditions (high winds, storms, snow, heavy rain or drought) and may occasionally fail without warning. It is therefore not possible to state with any certainty that any tree or group of trees is completely safe. The condition of a tree or group of trees can change rapidly as a result of external factors; we would advise that the occupier/ owners inspect the trees at least every 12 months or following periods of extreme weather and where concerns are raised relating to tree health that would be considered beyond the knowledge of a layperson, further arboricultural advice should be sought.

HAZARD SAFETY AUDIT

Client:	Bursledon Parish Council
Site	Long Lane Recreation Ground, Bursledon
Date of Survey:	4th September 2023 (Whole Site) 9th September 2024 (Re-inspection of T1-T4 and Grp 10)
Consultant:	Alexa Monk *TechCert (Arbor A) NCH Arb* Stefan Rose *BSc (Hons), TechCert (Arbor.A), TechArbor.A*
Tagged:	No

TREE PRESERVATION ORDER / CONSERVATION AREA:
CBA Trees has been informed by the client that trees are protected by a Tree Preservation Order and that they are located within The Old Bursledon Conservation Area.

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
1	Pedunculate Oak *Quercus robur*	M	15-20	>600	10-15	Good	Basal suckers Old pruning wounds on trunk and in crown Minor deadwood in crown Epicormics on trunk and in crown Ditch to north Trunk shape distorted Leans and weighted south Historically removed trunk on south side	No works required at time of survey	N/A	2 years
2	Pedunculate Oak *Quercus robur*	M	15-20	>600	10-15	Good	Old pruning wounds in crown Epicormics on trunk and in crown Ditch to south Branch tear wounds in crown Vegetation at base limits survey Possibly owned by No.9 Bursledon Heights	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
3	Pedunculate Oak *Quercus robur*	M	15-20	450-600	10-15	Good	Ivy on trunk Old pruning wounds on trunk and in crown Minor deadwood in crown Low hanging branches Bifurcated at 1.6m above ground level Branches close to roof and chimney	Reduce away from chimney to provide 2m clearance Reduce back to provide 2m separation to dwelling and roof line	Important - within 6 months	2 years
4	Pedunculate Oak *Quercus robur*	EM	10-15	450-600	5-10	Good	Ivy on trunk and in crown Old pruning wounds on trunk and in crown Minor deadwood in crown Branches close to roof and chimney (<50mm)	Reduce back to provide 2m separation to dwelling and roof line	Important - within 6 months	2 years
5	Wild Cherry *Prunus avium*	SM	5-10	150-300	5-10	Good	Old pruning wounds on trunk Minor deadwood in crown	No works required at time of survey	N/A	N/A
6	Wild Cherry *Prunus avium*	EM	5-10	150-300	5-10	Fair	Ivy on trunk and in crown Minor deadwood in crown Low crown density with apical dieback	Sever and remove ivy	Important - within 6 months	2 years
7	Pedunculate Oak *Quercus robur*	EM	10-15	300-450	5-10	Fair	Bifurcated at ground level Crown shape distorted Crossing and rubbing branches in crown Minor deadwood in crown Old pruning wounds on trunk and in crown Ivy on trunk Trunks fused together at 1.8m and 4m above ground level Branches fusing together within crown	No works required at time of survey	N/A	2 years
8	Common Ash *Fraxinus excelsior*	EM	10-15	300-450	10-15	Fair	Multi-stemmed at ground level Minor deadwood in crown Cankers forming in crown Previously crown reduced	No works required at time of survey	N/A	2 years
9	Pedunculate Oak *Quercus robur*	EM	15-20	300-450	10-15	Fair	Trunk and crown shape distorted due to group pressure Minor deadwood in crown Epicormics on trunk and in crown Leans and weighted west over building	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
9A	Common Ash *Fraxinus excelsior*	SM	5-10	<150	5-10	Fair	Regrowth from old stump Decay in stump Bifurcated at ground level	No works required at time of survey	N/A	2 years
10	Pedunculate Oak *Quercus robur*	M	10-15	450-600	10-15	Good	Major deadwood in crown over building at 7m above ground level Epicormics on trunk Old pruning wounds on trunk	Remove deadwood	Important - within 6 months	2 years
11	Pedunculate Oak *Quercus robur*	EM	10-15	300-450	10-15	Fair	Leans and weighted north Minor deadwood in crown	No works required at time of survey	N/A	2 years
12	Pedunculate Oak *Quercus robur*	M	15-20	300-450	15-20	Fair	Bifurcated at ground level Bark wounds at base Old pruning wounds	No works required at time of survey	N/A	2 years
13	Common Ash *Fraxinus excelsior*	EM	10-15	300-450	10-15	Fair	Growing on bank Trifurcated at 2m above ground level Tight forks with included bark Old pruning wounds on trunk Epicormics in crown Old pruning wounds in crown Major bark wound at base approximately 80% ring barked	Advise removal	Routine - within 12 months	N/A
14	Common Ash *Fraxinus excelsior*	EM	15-20	300-450	10-15	Fair	Growing on bank Epicormics on trunk and in crown Old pruning wounds with cavities Crossing and rubbing branches in crown Storm damage in crown Branch tear wounds in crown Minor deadwood in crown Crown rubbing on utility pole on south side	Prune clear of utility pole to provide 1m clearance	Important - within 6 months	2 years
15	Wild Cherry *Prunus avium*	M	5-10	300-450	15-20	Good	Mechanical damage to surface roots Old pruning wounds in crown Minor deadwood in crown	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
16	Wild Cherry *Prunus avium*	SM	5-10	150-300	5-10	Fair	Growing on bank Trifurcated at 1m above ground level Old pruning wounds in crown Crown shape distorted due to group pressure Dead ivy - previously cut Minor deadwood in crown	No works required at time of survey	N/A	2 years
17	London Plane *Platanus x acerifolia*	Y	5-10	<150	<5	Fair	Developing tree Bark wounds at base Old pruning wounds on trunk	Create mulch circle around base to prevent further damage and maintain mulch annually for 5 years	Necessary - within 3 months	2 years
18	Common Lime *Tilia x europaea*	SM	5-10	150-300	5-10	Fair	Mechanical damage to surface roots Basal suckers Epicormics on trunk and in crown Minor deadwood in crown Bifurcated at 3m above ground level with tight fork with included bark Bark wound on south side of trunk at 2.5m above ground level	Remove basal suckers	Routine - within 12 months	2 years
19	Previously removed	-	-	-	-	-	-	-	-	-
20	Wild Cherry *Prunus avium*	EM	10-15	300-450	10-15	Good	Mechanical damage to surface roots Old pruning wounds on trunk Minor deadwood in crown	No works required at time of survey	N/A	2 years
21	Common Sycamore *Acer pseudoplatanus*	EM	10-15	300-450	10-15	Fair	Mechanical damage to surface roots Trifurcated at 2.5m above ground level Minor deadwood in crown	No works required at time of survey	N/A	2 years
22	Wild Cherry *Prunus avium*	SM	5-10	<150	5-10	Fair	Bifurcated at 0.25m above ground level Tight forks with included bark Mechanical damage to surface roots Crossing and rubbing trunks Old pruning wounds on trunks	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
23	Wild Cherry *Prunus avium*	EM	5-10	300-450	10-15	Fair	Mechanical damage to surface roots Old pruning wounds on trunk	No works required at time of survey	N/A	2 years
24	Norway Maple *Acer platanoides*	SM	5-10	150-300	5-10	Good	Mechanical damage to surface roots Minor deadwood in crown	No works required at time of survey	N/A	2 years
25	Common Lime *Tilia x europaea*	SM	5-10	150-300	5-10	Good	Mechanical damage to surface roots Old pruning wounds on trunk and in crown Epicormics in crown Minor deadwood in crown Basal suckers	Remove basal suckers	Routine - within 12 months	2 years
26	Common Whitebeam *Sorbus aria*	SM	5-10	300-450	5-10	Fair	Mechanical damage to surface roots Multi-stemmed at 2m above ground level Old pruning wounds on trunk and in crown Minor deadwood in crown	No works required at time of survey	N/A	2 years
27	Silver Birch *Betula pendula*	SM	10-15	150-300	5-10	Good	Possibly offsite tree Growing on bank Minor deadwood in crown	No works required at time of survey	N/A	2 years
28	Goat Willow *Salix caprea*	SM	10-15	300-450	10-15	Fair	Possibly offsite tree Growing on bank Minor deadwood in crown Crown interferes with utility pole on south side	Prune clear of utility pole to provide 1m clearance	Important - within 6 months	2 years
29	Goat Willow *Salix caprea*	SM	<5	<150	<5	Fair	Possibly offsite tree Growing on bank at base of utility pole Minor deadwood in crown	Prune clear of utility pole to provide 1m clearance	Important - within 6 months	2 years
30	Wild Cherry *Prunus avium*	EM	10-15	150-300	10-15	Fair	Trifurcated at 1m above ground level Old pruning wounds on trunk and in crown Minor deadwood in crown Tight forks with included bark Bleeding canker on trunk	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
31	Wild Cherry *Prunus avium*	EM	10-15	150-300	10-15	Fair	Mechanical damage to surface roots Multi-stemmed at 0.5m above ground level Tight forks with included bark Old pruning wounds on trunk and in crown Bleeding canker on trunk Crossing and rubbing branches	No works required at time of survey	N/A	2 years
32	Common Alder *Alnus glutinosa*	SM	5-10	150-300	5-10	Fair	Multi-stemmed at 1m above ground level Old pruning wounds on trunk and in crown Mechanical damage to surface roots Bleeding canker on trunk Bark wounds at base	No works required at time of survey	N/A	2 years
33	Pedunculate Oak *Quercus robur*	EM	10-15	300-450	10-15	Good	Possibly offsite tree Growing on bank Dead ivy on trunk and in crown Minor deadwood in crown	No works required at time of survey	N/A	2 years
34	Pedunculate Oak *Quercus robur*	EM	10-15	450-600	15-20	Good	Possibly offsite tree Ivy on trunk Trunk shape distorted Major deadwood in crown Epicormics in crown Exposed surface roots	If owned remove deadwood	Important - within 6 months	2 years
35	Horse Chestnut *Aesculus hippocastanum*	SM	5-10	150-300	5-10	Fair	Bleeding canker on trunk Old pruning wounds on trunk and in crown Bark wound at base on east side	No works required at time of survey	N/A	2 years
36	Horse Chestnut *Aesculus hippocastanum*	SM	5-10	150-300	5-10	Fair	Bifurcated at 0.5m above ground level Epicormics on trunk and in crown Bark wounds on trunk Low hanging branches Mechanical damage to surface roots Crown starting to obstruct road sign on west side	Prune clear of road sign to provide 1m clearance	Necessary - within 3 months	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
37	Myrobalan Plum *Prunus cerasifera*	EM	10-15	150-300	5-10	Fair	Ivy on trunk and in crown Crown shape distorted due to group pressure Weighted north Storm damage in crown Minor deadwood in crown Previously crown reduced Leans and weighted over tennis court entrance	No works required at time of survey	N/A	2 years
38	Common Ash *Fraxinus excelsior*	EM	15-20	300-450	10-15	Good	Bifurcated at ground level Low hanging branches Basal suckers Minor deadwood in crown Weighted north	No works required at time of survey	N/A	2 years
39	Myrobalan Plum *Prunus cerasifera*	M	5-10	150-300	5-10	Dead	Dead tree	Advise removal	Necessary - within 3 months	2 years
40	Common Ash *Fraxinus excelsior*	SM	15-20	300-450	5-10	Fair	Trunk and crown shape distorted due to group pressure Ivy on trunk, regrowing Minor deadwood in crown	No works required at time of survey	N/A	2 years
41	Common Ash *Fraxinus excelsior*	SM	15-20	300-450	10-15	Good	Dead ivy on trunk - previously cut Bifurcated at 6m above ground level Minor deadwood in crown Growing on boundary	No works required at time of survey	N/A	2 years
42	Common Ash *Fraxinus excelsior*	EM	15-20	300-450	10-15	Fair	Bifurcated at ground level Crown shape distorted due to group pressure Minor deadwood in crown Dead ivy on trunk - previously cut	No works required at time of survey	N/A	2 years
43	Common Ash *Fraxinus excelsior*	SM	10-15	150-300	10-15	Fair	Bifurcated at ground level Crown shape distorted due to group pressure Minor deadwood in crown	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
44	Pedunculate Oak *Quercus robur*	M	15-20	450-600	10-15	Fair	Leans north Trunk and crown shape distorted due to group pressure Epicormics on trunk and in crown Major deadwood in crown on north west side at 7m above ground level	Remove deadwood	Important - within 6 months	2 years
44A	Bay Laurel *Laurus nobilis*	SM	5-10	150-300	5-10	Good	Multi-stemmed at ground level	No works required at time of survey	N/A	2 years
45	Common Ash Sycamore	SM	10-15	150-300	10-15	Fair	Two trees growing next to one another Basal suckers Old pruning wounds on trunks and in crowns Trunk and crown shapes distorted due to group pressure Major deadwood in crowns Dead epicormics in crown of dying Ash tree (90% dead)	Advise removal of dead/dying Ash tree	Important - within 6 months	2 years
46	Pedunculate Oak *Quercus robur*	SM	10-15	300-450	10-15	Fair	Leans and weighted north Minor deadwood in crown Epicormics in crown Adjacent Hawthorn leans into Oak	No works required at time of survey	N/A	2 years
47	Common Ash *Fraxinus excelsior*	SM	10-15	150-300	5-10	Fair	Bifurcated at 2.5m above ground level Ivy on trunk Minor deadwood in crown Tall and etiolated due to group pressure	No works required at time of survey	N/A	2 years
48	Previously removed	-	-	-	-	-	-	-	-	-
49	Pedunculate Oak *Quercus robur*	SM	5-10	150-300	5-10	Good	Bifurcated at 1.25m above ground level Trunk shape distorted	No works required at time of survey	N/A	2 years
50	Common Ash *Fraxinus excelsior*	Y	5-10	<150	<5	Fair	Trunk and crown shape distorted due to group pressure Minor deadwood in crown Developing tree	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
51	Bay Laurel *Laurus nobilis*	M	5-10	150-300	5-10	Fair	Multi-stemmed at ground level Basal suckers Growing at base of boundary wall	Consider removal to avoid future damage to wall	Routine - within 12 months	2 years
52	Pedunculate Oak *Quercus robur*	SM	10-15	150-300	5-10	Fair	Growing at base of boundary wall Growing beneath T53 Trunk and crown shape distorted due to group pressure Weighted west Minor deadwood in crown Branches touch roof of neighbouring building	Crown lift off neighbouring roof line to provide 1.5-2m separation	Routine - within 12 months	2 years
53	Common Ash *Fraxinus excelsior*	EM	15-20	300-450	10-15	Good	Growing at base of boundary wall Crown shape distorted due to group pressure Epicormics in crown Minor deadwood in crown Branches touch roof of neighbouring property	Crown lift off neighbouring roof line to provide 1.5-2m separation	Routine - within 12 months	2 years
54	Common Ash *Fraxinus excelsior*	M	15-20	450-600	15-20	Good	Growing at base of boundary wall Ivy on trunk Old pruning wounds on trunk and in crown Major deadwood in crown but no significant target Epicormics on trunk and in crown	No works required at time of survey	N/A	2 years
55	Pedunculate Oak *Quercus robur*	EM	15-20	300-450	15-20	Fair	Growing at base of boundary wall Bifurcated at 6m above ground level Crown shape distorted due to group pressure Major deadwood in crown but no significant target	No works required at time of survey	N/A	2 years
56	Common Ash *Fraxinus excelsior*	SM	15-20	150-300	10-15	Fair	Bifurcated at ground level Weighted south Minor deadwood in crown	No works required at time of survey	N/A	2 years
57	Pedunculate Oak *Quercus robur*	EM	15-20	450-600	10-15	Fair	Crown shape distorted due to group pressure Weighted north Minor deadwood in crown	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
58	Wild Cherry *Prunus avium*	SM	10-15	150-300	5-10	Fair	Two trees growing as one Crown shape distorted due to group pressure	No works required at time of survey	N/A	2 years
59	Wild Cherry *Prunus avium*	SM	10-15	150-300	5-10	Fair	Dead ivy on trunk and in crown Trunk and crown shape distorted due to group pressure Weighted north west Minor deadwood in crown	Clear around base	Routine - within 12 months	2 years
60	Wild Cherry x2 *Prunus avium*	EM	10-15	150-300	5-10	Fair	Dead ivy on trunks and in crowns - previously cut Crown shape distorted due to group pressure	No works required at time of survey	N/A	2 years
61	Pedunculate Oak *Quercus robur*	M	15-20	450-600	15-20	Good	Trunk and crown shape distorted due to group pressure Minor deadwood in crown Trifurcated at 5m above ground level	No works required at time of survey	N/A	2 years
61A	Elm *Ulmus spp*	SM	10-15	150-300	5-10	Fair	Tall and etiolated due to group pressure Basal suckers Ivy on trunk and in crown Minor deadwood in crown	No works required at time of survey	N/A	2 years
62	Pedunculate Oak *Quercus robur*	M	15-20	>600	10-15	Fair	Offsite tree Ivy on trunk Minor deadwood in crown Bifurcated at 2.5m above ground level Old pruning wounds on trunk and in crown	No works required at time of survey	N/A	2 years
63	Pedunculate Oak *Quercus robur*	EM	15-20	300-450	10-15	Fair	Appears to grow offsite Old pruning wounds on trunk and in crown Minor deadwood in crown Hung up branch in north side of crown	No works required at time of survey	N/A	2 years
64	Pedunculate Oak *Quercus robur*	EM	15-20	300-450	10-15	Fair	Crown shape distorted due to group pressure Weighted north Ivy on trunk Minor deadwood in crown	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
65	Pedunculate Oak *Quercus robur*	M	15-20	>600	15-20	Fair	Possibly offsite tree Unable to verify health and safety due to no access Growing on bank Multi-stemmed at approximately 3m above ground level Epicormics in crown Thinning crown - appears to be in decline	No works required at time of survey	N/A	2 years
66	Wild Cherry *Prunus avium*	SM	5-10	<150	5-10	Fair	Growing on bank by site gate Old pruning wounds on trunk Weighted north west Ivy on trunk	No works required at time of survey	N/A	2 years
67	Pedunculate Oak *Quercus robur*	SM	10-15	300-450	10-15	Fair	Trifurcated at 2.5m above ground level Storm damage in south side of crown Minor deadwood in crown Branch tear wound in crown at 3.5m above ground level	No works required at time of survey	N/A	2 years
68	Silver Birch *Betula pendula*	EM	10-15	150-300	5-10	Good	Old pruning wounds on trunk Minor deadwood in crown Branch tear out wounds in crown Bifurcated at 5m above ground level	No works required at time of survey	N/A	2 years
69	Field Maple *Acer campestre*	EM	5-10	150-300	5-10	Good	Ivy on trunk Minor deadwood in crown	Sever ivy	Routine - within 12 months	2 years
70	Crab Apple *Malus sylvestris*	SM	5-10	150-300	5-10	Good	Basal suckers Ivy on trunk Minor deadwood in crown Trifurcated at 3m above ground level	Sever ivy	Routine - within 12 months	2 years
71	Bay Laurel *Laurus nobilis*	SM	5-10	<150	5-10	Fair	Multi-stemmed at ground level Basal suckers	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
72	Common Hawthorn *Crataegus monogyna*	EM	5-10	<150	5-10	Fair	Multi-stemmed at ground level Historically reduced Epicormics on trunk and in crown Minor deadwood in crown	No works required at time of survey	N/A	2 years
73	Common Hawthorn *Crataegus monogyna*	SM	5-10	<150	<5	Fair	Multi-stemmed at ground level Historically reduced Epicormics on trunk and in crown Minor deadwood in crown Old pruning wounds on trunk	No works required at time of survey	N/A	2 years
74	Common Sycamore *Acer pseudoplatanus*	Y	5-10	<150	<5	Fair	Bifurcated at 2.5m above ground level Developing tree	No works required at time of survey	N/A	2 years
75	Flowering Cherry *Prunus spp*	SM	5-10	150-300	5-10	Fair	Old pruning wounds on trunk Crown shape distorted due to group pressure	No works required at time of survey	N/A	2 years
76	Rowan *Sorbus aucuparia*	SM	5-10	<150	<5	Good	Developing tree Trunk shape distorted	No works required at time of survey	N/A	2 years
77	Flowering Cherry *Prunus spp*	SM	5-10	<150	5-10	Fair	Leans and weighted east Minor deadwood in crown Previously bifurcated at ground level but one stem removed	No works required at time of survey	N/A	2 years
78	Flowering Cherry *Prunus spp*	SM	5-10	<150	<5	Fair	Bifurcated at ground level Minor deadwood in crown	No works required at time of survey	N/A	2 years
79	Field Maple *Acer campestre*	SM	5-10	<150	5-10	Fair	Bifurcated at 1m above ground level Developing tree	No works required at time of survey	N/A	2 years
80	Rowan *Sorbus aucuparia*	SM	5-10	<150	<5	Fair	Trunk shape distorted Previously crown reduced Multi-stemmed at 2.1m above ground level	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
Grp 1	Silver Birch Goat Willow Common Ash Scots Pine	SM	10-15	150-300	5-10	Good	Possibly offsite group Growing on bank by site entrance Unable to verify health and safety due to no access and dense vegetation Trunk and crown shapes distorted due to group pressure Ivy on trunks Minor deadwood in crowns	No works required at time of survey	N/A	2 years
Grp 2	Rowan Wild Cherry Common Hawthorn	SM	<5	<150	5-10	Fair	Multi-stemmed at ground level Tight forks with included bark	No works required at time of survey	N/A	2 years
Grp 3	Goat Willow	EM	5-10	150-300	10-15	Fair	Possibly offsite group Growing on bank Multi-stemmed at ground level Low hanging branches Ivy on trunks Minor deadwood in crowns	No works required at time of survey	N/A	2 years
Grp 4	Common Ash x3 Field Maple x1 Pedunculate Oak x1 Common Holly x1 Flowering Cherry x1	SM	5-10	<150	5-10	Fair	Bark wounds in crown Some trees multi-stemmed at various heights Crown shape distorted due to group pressure Ivy on trunks Old pruning wounds on trunk and in crown One large Oak between substation fencing has minor deadwood in crown and unable to verify health and safety due to no access	No works required at time of survey	N/A	2 years
Grp 5	Myrobalan Plum Lawson Cypress Blackthorn	SM	<5	150-300	5-10	Fair	Some historically wind blown Old pruning wounds on trunks and in crowns Epicormics on trunks and in crowns	No works required at time of survey	N/A	2 years
Grp 6	Myrobalan Plum	EM	5-10	150-300	5-10	Fair	Basal suckers Ivy on trunks, regrowing Some multi-stemmed at various heights Old pruning wounds on trunks and in crowns	No works required at time of survey	N/A	2 years

Tree No	Species	Age Class	Height (m)	Trunk Diameter (mm)	Crown Spread (m)	Overall Condition	Defects and other Relevant Comments	Recommended Works	Priority (months)	Recommended Re-inspection Interval
Grp 7	Wild Cherry Dogwood Pedunculate Oak Common Beech Hawthorn	SM	5-10	150-300	<5	Good	Trunk and crown shapes distorted due to group pressure Low hanging branches Ivy on trunks Minor deadwood in crowns Developing trees	No works required at time of survey	N/A	2 years
Grp 8	Silver Birch Field Maple Pedunculate Oak Horse Chestnut Myrobalan Plum	SM	10-15	150-300	<5	Fair	Trunk and crown shapes distorted due to group pressure Low hanging branches Ivy on trunks Minor deadwood in crowns	No works required at time of survey	N/A	2 years
Grp 9	Rhus Elder Common Ash Myrobalan Plum Common Holly	SM	5-10	150-300	5-10	Fair	Understorey to more mature trees Trunk and crown shape distorted due to group pressure Low hanging branches Minor deadwood in crowns Ivy on trunks and in crowns limits survey of some trees	No works required at time of survey	N/A	2 years
Grp 10	Field Maple x1 Pedunculate Oak x2	EM	10-15	150-300	5-10	Fair	Trunk and crown shapes distorted due to group pressure Ivy on trunks Minor deadwood in crowns Low hanging branches	Sever ivy Lift on east side/ garden side by removing epicormics on Field Maple and lowest two branches on east side at approximately 5m	Routine - within 12 months	2 years
Grp 11	Blackthorn Hazel Wild Cherry Bay Laurel Hawthorn Horse Chestnut	SM	5-10	<150	<5	Good	Growing along site boundary Lower crown clipped back Trunk and crown shapes distorted due to group pressure Several trees starting to form individually Some trees multi-stemmed at ground level	Continue regular maintenance	Routine - within 12 months	2 years
Grp 12	Cherry Laurel Bay Laurel	SM	5-10	<150	5-10	Good	Multi-stemmed at ground level Some branches previously cut and responding well to form dense lower level hedging Some branches beginning to touch boundary wall	Lift/ reduce branches on south side to clear boundary wall and provide approximately 1-1.5m separation	Routine - within 12 months	2 years



EASTLEIGH BOROUGH COUNCIL

Title

Recreational Ground

Long Lane

CBA Trees
Chesil House, Arrow Close
Boyatt Wood, Hampshire, SO50 4SY
Tel: 02380 986229
Email: info@cbatrees.co.uk
Web: www.cbatrees.co.uk

CBA11083LLRG
Long Lane Recreation Ground, Bursledon
Tree Location Plan

SCALE : NOT TO SCALE	**DATE :** 07/09/2023	N
MAP FILENAME : CBA11083LLRG.01B TLP		

Map data shown may contain Ordnance Survey ® products supplied by Pear Technology Services Ltd; Email: info@peartechnology.co.uk
© Crown Copyright and database rights from date shown above
Ordnance Survey ® licence number 100023148

NOTE: ALL TREES AND GROUPS ARE INDICATIVELY PLOTTED

TREE PRESERVATION ORDER / CONSERVATION AREA:
CBA TREES HAS BEEN INFORMED BY THE CLIENT THAT TREES ARE PROTECTED BY A TREE PRESERVATION ORDER AND THAT THEY ARE LOCATED WITHIN THE OLD BURSLEDON CONSERVATION AREA

✕ TREES THAT HAVE BEEN PREVIOUSLY REMOVED

CB1

The Professional Arboricultural Consultancy

Company Profile, Qualifications and Experience

CBA Trees is acknowledged as one of the UK's leading arboricultural consultancies offering a full range of tree related services from BS5837 tree surveys, arboricultural impact assessments and method statements to health and safety audits. Based near Southampton in Hampshire with easy access to the motorway network and transport links, we provide a professional solution to your tree problem throughout southern England and nationwide across the UK.

Whether the instruction is in respect of a single tree in a garden, a mortgage report, a development site or a new settlement that needs a full arboricultural report for a planning application, CBA Trees has the tree expertise to provide a professional solution. We employ a team of qualified and experienced arboricultural consultants to ensure that at every stage of the arboricultural process our clients receive the very best in expert knowledge and the highest standard of professional service.

Stefan Rose *BSc(Hons), TechCert (Arbor A), TechArbor.A* joined CBA Trees in 1998 as a junior surveyor and having gained extensive knowledge and a wealth of experience over the years including the Professional Tree Inspectors Certification (LANTRA), has progressed to Principal Consultant. His vast experience in working as a locum for local authorities, assessing new and extant Tree Preservation Orders, as well as working on some of the largest development sites nationwide enables him to provide expert advice and guidance on initial feasibility site assessments to full scale planning applications, working with individual homeowners and within multi-disciplinary teams to achieve successful arboricultural outcomes.

Dominic Poston *F.Arbor.A. MICFor, CEnv, Prof Dip (RFS), BSc (Hons), HND* joined CBA Trees in 2015 as a Senior Consultant and brings with him a wealth of knowledge and experience. Having attained a Bachelor of Science Degree in Horticulture, a Higher National Diploma in Landscape Management and the Royal Forestry Society's Professional Diploma in Arboriculture, Dominic is a fellow of the Arboricultural Association and a Chartered Arboriculturist and Chartered Environmentalist. Through local authority experience he has been involved as a supervising officer and advisor to planning teams on many developments near trees. Through private sector experience he has provided arboricultural advice, ranging from feasibility through to implementation on many development projects near trees. He has extensive experience in the management of large tree stocks, implementing the recommendations within BS5837 and acting as an expert witness. He has considerable experience working closely with clients and as part of a multi-disciplinary team.

Alexa Monk *TechCert (Arbor.A), NCH.Arb* has a background in tree surgery, running her own small business for many years. Working with CBA Trees for over 10 years, Alexa has experience of pre-planning work for developers, Tree Preservation Order legislation work, tree inspection including decay detection with sophisticated decay detection equipment and general arboricultural health and safety surveys.

Joe Beznosiuk *Dip Arb L4 (ABC)* the newest member of our team, Joe started his career as a tree surgeon before he made the transition into consultancy 10 years ago, where he has worked for both local authorities and private consultancies, providing a wide range of arboricultural advice, which has involved tree stock management, development projects in relation to BS5837, planning advice and Health and Safety risk assessment surveys.

Listed below are some of the services we provide:

- Arboricultural Consultancy
- BS5837 tree surveys (for residential sites and development projects)
- Arboricultural Impact Assessments and Method Statements
- Advice on Tree Preservation Orders including Objections
- Arboricultural Health and Safety Surveys
- Arboricultural site and project management

CBA Trees is very proud of its client base which includes the following companies:

Acorn Tree Specialist Ltd
Ampfield Parish Council
Burseldon Parish Council
Contractual Ltd
Crest Strategic Properties
Croudace
David Wilson Homes
Dhand Construction Ltd
Drew Smith Group
Draycott Chartered Surveyor
Eastleigh Borough Council
English Heritage Trust
Genesis Design Studio
Gillings Planning
Knight Architectural Design
Lakewood Tree Surgeons
NHS Property Services
Portsmouth City Council
Radian
Southampton City Council
SLR Consulting Ltd
Taylor Wimpey
University of Portsmouth
University of Winchester
Unsted Design
West Wittering Parish Council
Whiterok Architectural Services Ltd

CBA Trees can be found at:

Chesil House
Arrow Close
Boyatt Wood
Hampshire
SO50 4SY

Tel: 02380 986229
Email: info@cbatrees.co.uk

For further information visit our website at www.cbatrees.co.uk which provides more detail on our expertise, and of course, our team are always willing to help answer any queries you may have.