

Site: Hamble Common & Green											
Tree no.	Species	Location	Ht (m)	1st Stem Diameter (mm)	2nd Stem	Age Class	Physiological condition	Structural condition	Preliminary Recommendations	Priority rating	Notes
T1	Sycamore	South of path	24	780		Ma	Good to fair	Good to fair	Cavity. Leans east. No further action at this time	Noted	
T2	Sycamore	By path,n	20	900,ms		Oma	Fair to poor	Fair to poor	Split stem on east side. Early defoliation	Noted	
T3	Silver maple	By path	22	1m,ms		Ma	Fair to poor	Fair to poor	Very sparse at top section.	Woodland management plan recommends removal and replant.	
T4	Scots pine	By path	20	600		Ma	Brown throughout canopy. Drought response.	Deadwood over path.	Remove deadwood over path	2 - within one year	
T5	Beech	By path junction	18	680			Fair. Ganoderma resinaceum on multiple points round stem . Very sparse throughout.	Fair	Good habitat, plan to reduce in next few years	3- within next inspection interval or as resources allow.	
T6	Ash.	Corner of entrance to Ferry House.	19	50		Ma	Fair to good, Pseudomonotus north side of main stem at 7m	Fair but compromised	Fell	1- within 3 months. Foreseeable failure.	

Tree location map on following pages

