

Your ref LIV-SN-22-005467


Our ref 09303GLOB

Geo-Serv Limited
17 Hoveden Road
London NW2 3XE

tel: 020 8208 0343

email: mon@geo-serv.com

**Subsidence
Monitoring
Services**



GEO-SERV

360Globalnet Ltd
Bramley House,
Bramley Road,
Long Eaton,
NG10 3SX

Issue date: 23/07/2026

Monitoring visit 10 of tbc

Monitoring Plus Report

Owners name	Ms S Berrett	Suspected cause	to be advised	Monitoring type	levels & cracks
Address	27 The Foxgloves Hedge End Southampton SO30 0UG	Principal area of damage	to be advised	Installed	09/06/2023
		Damage category	to be advised	Frequency (weeks)	8.0
		Surface geology	to be advised	Completion date	tbc
				Status	open
Comment	Feedback from last visit				
Max moveme 12.0 mm	no feedback for this visit				
Focal area Pts 4r, 5r, 6r, 7r, 8,					
0	Sketch showing location of monitoring points				

Crack monitoring results

Survey:		1		2		3		4		5	
By:		VV		VV		VV		VV		Vanya	
Date:	initial	09/06/2023		08/08/2023		14/12/2023		22/02/2024		03/05/2024	
Crack ID	width mm	sprtn	chngs	sprtn	chngs	sprtn	chngs	sprtn	chngs	levels	chngs
		mm	mm	mm	mm	mm	mm	mm	mm	mm	mm
A (horiz)	3.20	74.65	0.0	77.21	2.6	75.86	1.2	75.79	1.1	75.77	1.1
A (diag)		151.90	0.0	148.88	-3.0	150.91	-1.0	151.15	-0.8	151.16	-0.7
A (check)		135.51	0.0	135.46	0.0	135.46	0.0	135.48	0.0	135.52	0.0

all measurements made with internal jaws unless marked with asterisk, ^ = angle bracket, \$ = measurement with butt end of calipers



crack descriptions

A (horiz) Demec triplet, internal, conservatory.

Survey:		6		7		8		9		10	
By:		Vanya		Vanya		Vanya		Vanya		Vanya	
Date:	initial	13/11/2025		23/01/2026		17/03/2026		21/05/2026		23/07/2026	
Crack ID	width mm	sprtn	chngs	sprtn	chngs	sprtn	chngs	sprtn	chngs	levels	chngs
		mm	mm	mm	mm	mm	mm	mm	mm	mm	mm
A (horiz)	3.2	51.94	0.0	52.26	0.3	51.89	0.0	51.76	-0.2	52.24	0.3
A (diag)		60.01	0.0	60.04	0.0	60.12	0.1	59.99	0.0	60.11	0.1
A (check)		33.59	0.0	33.62	0.0	33.60	0.0	33.60	0.0	33.57	0.0

all measurements made with internal jaws unless marked with asterisk, ^ = angle bracket, \$ = measurement with butt end of calipers

Crack monitoring



Level Monitoring Results

Survey:	1 VV		2 VV		3 VV		4 VV		5 Vanya	
By:										
Date:	09/06/2023		08/08/2023		14/12/2023		22/02/2024		03/05/2024	
Point ID	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm
1	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0
2r	1491.79	0.0	1487.72	-4.1	1490.52	-1.3	1491.04	-0.7	1490.53	-1.3
3cill	873.34	0.0	869.80	-3.5	872.45	-0.9	872.77	-0.6	872.84	-0.5
4r	1483.37	0.0	1477.99	-5.4	1482.38	-1.0	1482.77	-0.6	1482.74	-0.6
5r	1483.47	0.0	1478.42	-5.1	1482.26	-1.2	1482.73	-0.7	1483.27	-0.2
6r	1484.56	0.0	1481.22	-3.3	1483.65	-0.9	1484.07	-0.5	1484.35	-0.2
7r	1486.75	0.0	1483.82	-2.9	1486.22	-0.5	1486.72	0.0	1486.94	0.2
8	936.23	0.0	933.62	-2.6	936.92	0.7	937.43	1.2	937.29	1.1

closing error (mm)

0.00

0.00

0.00

0.00

0.00

Survey:	6 Vanya		7 Vanya		8 Vanya		9 Vanya		10 Vanya	
By:										
Date:	13/11/2025		23/01/2026		17/03/2026		21/05/2026		23/07/2026	
Point ID	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm	levels mm	chngs mm
1	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0	1000.00	0.0
2r	1489.69	-2.1	1492.32	0.5	1491.73	-0.1	1491.70	-0.1	1489.51	-2.3
3cill	869.33	-4.0	872.68	-0.7	872.82	-0.5	872.98	-0.4	866.91	-6.4
4r	1480.29	-3.1	1480.96	-2.4	1481.03	-2.3	1480.47	-2.9	1474.86	-8.5
5r	1481.01	-2.5	1481.18	-2.3	1481.55	-1.9	1481.19	-2.3	1475.66	-7.8
6r	1482.25	-2.3	1482.81	-1.8	1482.75	-1.8	1482.36	-2.2	1474.96	-9.6
7r	1484.77	-2.0	1485.47	-1.3	1485.43	-1.3	1485.19	-1.6	1475.14	-11.6
8	934.47	-1.8	935.72	-0.5	935.79	-0.4	935.82	-0.4	925.47	-10.8

closing error (mm)

0.00


0.00

0.00

0.00

0.00

Precise level monitoring related to Point 1



Photos for report

