

Project-information

Project name :
143and145PASSFIELD AVENUE

Project Number :

Contact :

Date :
30/01/2023

Client: **MARCO TEAGUE**

Contact Name:

Department:

Road:

Town:

County:

Telephone:

Fax:

Mobile:

E-mail:

Site: **143 - 145 PASSFIELD AVENUE**

Contact Name:

Department:

Road: **PASSFIELD AVENUE**

Town: **EASTLEIGH**

County: **HAMPSHIRE SO50 9NH**

Telephone:

Fax:

Mobile:

E-mail:

Contractor **A1 DRAINAGE**

Contact Name: **ALAN SMITH**

Department:

Road: **ROYSTON AVENUE**

Town: **EASTLEIGH**

County: **HAMPSHIRE**

Telephone: **02380 610413**

Fax:

Mobile:

E-mail: **a1drainagesouth@yahoo.com**

Date : 30/01/2023	Job number :	Section Type :	Operator : A SMITH	Section number : 1	PLR SUFFIX:
Weather no rain or snow	Vehicle :	Camera :	Preset :	Cleaned : no	Type of Drain : Gravity drain/sewer

Place :	EASTLEIGH	Location details:	U/S MH :	LATERAL 1
Road :	143 - 145 PASSFIELD AVENUE	Catchment:	U/S Depth :	0.0
Location	Gardens	Pipe Shape :	D/S MH :	F1
Inspection	F1 (U/S) LATERAL 1	Pipe Length	D/S Depth :	0.77

Use:	Foul	Pipe Width :	
Year laid :		Pipe Diameter :	100 mm
Purpose :	Sample survey to determine asset condition	Pipe material :	Polyvinyl chloride
Total length :	3.19 m	Lining :	

Comment : **MANHOLES LOCATED AT REAR OF PROPERTY**

1:50	Position	Observation	Photo
	Depth: 0.77	Start node type manhole reference number: F1 Water level 00 % of the vertical dimension Finish node type outfall reference number: LATERAL 1 INTERNAL WASTE STACK	20230130-082242-snap0000.jpg 20230130-082242-snap0001.jpg

[illegible]

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
1

PLR Suffix :



Photo: 20230130-082242-snap0000.jpg, 00:00:07
0.11m, Start node type manhole reference number: F1



Photo: 20230130-082242-snap0001.jpg, 00:00:58
3.19m, Finish node type outfall reference number: LATERAL 1 INTERNAL WASTE
STACK

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
2

PLR Suffix :



Photo: 20230130-082500-snap0000.jpg, 00:00:01
0m, Start node type manhole reference number: F1



Photo: 20230130-082500-snap0001.jpg, 00:00:29
0.95m, Junction from/at 12 o'clock diameter: 100 mm

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
2

PLR Suffix :



Photo: 20230130-082500-snap0002.jpg, 00:01:58
2.58m, Finish node type outfall reference number: LATERAL 2 INTERNAL WASTE
STACK


Inspection report

Date : 30/01/2023	Job number :	Section Type :	Operator : A SMITH	Section number : 3	PLR SUFFIX:
Weather no rain or snow	Vehicle :	Camera :	Preset :	Cleaned : no	Type of Drain : Gravity drain/sewer

Place : Road : Location Inspection	EASTLEIGH 143 - 145 PASSFIELD AVENUE Gardens F1 (D/S) DSTREAM	Location details: Catchment: Pipe Shape : Pipe Length	Circular 0.00 m	U/S MH : U/S Depth : D/S MH : D/S Depth :	F1 0.0 DSTREAM 0.0
---	--	--	----------------------------	--	---------------------------------------

Use: Year laid : Purpose : Total length :	Foul Sample survey to determine asset condition 2.96 m	Pipe Width : Pipe Diameter : Pipe material : Lining :	 150 mm Vitrified clay
--	--	--	--

Comment :	MANHOLES LOCATED AT REAR OF PROPERTY
-----------	---

1:50	Position	Observation	Photo						
Depth: 0.0									
	0.00	Start node type manhole reference number: F1	20230130-082748-snap0000.jpg						
	0.00	Water level 00 % of the vertical dimension							
	0.53	Junction from/at 10 o'clock diameter: 100 mm	20230130-082748-snap0001.jpg						
	2.96	Survey abandoned Remarks: ROOT BLOCKAGE IN PIPE	20230130-082748-snap0002.jpg						
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
3

PLR Suffix :



Photo: 20230130-082748-snap0000.jpg, 00:00:02
0m, Start node type manhole reference number: F1



Photo: 20230130-082748-snap0001.jpg, 00:00:25
0.53m, Junction from/at 10 o'clock diameter: 100 mm

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
3

PLR Suffix :



Photo: 20230130-082748-snap0002.jpg, 00:00:56
2.96m, Survey abandoned Remarks: ROOT BLOCKAGE IN PIPE


Inspection report

Date : 30/01/2023	Job number :	Section Type :	Operator : A SMITH	Section number : 4	PLR SUFFIX:
Weather no rain or snow	Vehicle :	Camera :	Preset :	Cleaned : no	Type of Drain : Gravity drain/sewer

Place : Road : Location Inspection	EASTLEIGH 143 - 145 PASSFIELD AVENUE Gardens F2 (U/S) UPSTREAM	Location details: Catchment: Pipe Shape : Pipe Length	 Circular 0.00 m	U/S MH : U/S Depth : D/S MH : D/S Depth :	UPSTREAM 0.0 F2 0.90
---	---	--	--	--	---

Use: Year laid : Purpose : Total length :	Foul Sample survey to determine asset condition 4.67 m	Pipe Width : Pipe Diameter : Pipe material : Lining :	 100 mm Vitrified clay
--	---	--	--

Comment :	MANHOLES LOCATED AT REAR OF PROPERTY
-----------	---

1:50 Depth: 0.90	Position	Observation	Photo
	F2	Start node type manhole reference number: F2	20230130-083212-snap0000.jpg
	0.00	Water level 05 % of the vertical dimension	20230130-083212-snap0001.jpg
	1.41	Junction from/at 02 o'clock diameter: 100 mm	20230130-083212-snap0002.jpg
	2.51	Junction from/at 02 o'clock diameter: 100 mm	20230130-083212-snap0003.jpg
	4.67	Finish node type outfall reference number: UPSTREAM INTERNAL WASTE STACK	20230130-083212-snap0004.jpg
UPSTREAM Depth: 0.0			

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
------------	----------	----------	-----------	-----------	------------	----------	----------	-----------	-----------

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
4

PLR Suffix :



Photo: 20230130-083212-snap0000.jpg, 00:00:04
0m, Start node type manhole reference number: F2



Photo: 20230130-083212-snap0001.jpg, 00:00:07
0m, Water level 05 % of the vertical dimension

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
4

PLR Suffix :



Photo: 20230130-083212-snap0002.jpg, 00:00:26
1.41m, Junction from/at 02 o'clock diameter: 100 mm



Photo: 20230130-083212-snap0003.jpg, 00:01:01
2.51m, Junction from/at 02 o'clock diameter: 100 mm

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
4

PLR Suffix :



Photo: 20230130-083212-snap0004.jpg, 00:01:41

4.67m, Finish node type outfall reference number: UPSTREAM INTERNAL WASTE
STACK

Date : 30/01/2023	Job number :	Section Type :	Operator : A SMITH	Section number : 5	PLR SUFFIX:
Weather no rain or snow	Vehicle :	Camera :	Preset :	Cleaned : no	Type of Drain : Gravity drain/sewer

Place :	EASTLEIGH	Location details:	U/S MH :	F2
Road :	143 - 145 PASSFIELD AVENUE	Catchment:	U/S Depth :	0.90
Location	Gardens	Pipe Shape :	D/S MH :	DSTREAM
Inspection	F2 (D/S) DSTREAM	Pipe Length	D/S Depth :	0.0

Use:	Foul	Pipe Width :	
Year laid :		Pipe Diameter :	100 mm
Purpose :	Sample survey to determine asset condition	Pipe material :	Vitrified clay
Total length :	3.99 m	Lining :	

1:50	Position	Observation	Photo
Depth: 0.90			
	0.38	Joint displaced medium	20230130-083451-snap0001.jpg
	0.38	Cracks multiple at joint from/at 07 o'clock to 02 o'clock	20230130-083451-snap0002.jpg
	0.91	Line deviates left Remarks: DROPPING INTO PIPE RUNNING FROM MANHOLE F1	20230130-083451-snap0003.jpg
	1.52	Size changes new size(s) 150 mm high 150 mm wide	20230130-083451-snap0004.jpg
	2.47	Line deviates left	20230130-083451-snap0005.jpg
	3.08	Finish node type manhole reference number: DSTREAM INTO F3 MAIN SEWER Remarks: LOCATED IN GARDEN OF NEIGHBOUR. UNABLE TO LOCATE	20230130-083451-snap0006.jpg
Depth: 0.0			

[illegible]

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
5

PLR Suffix :



Photo: 20230130-083451-snap0000.jpg, 00:00:00
-0.91m, Start node type manhole reference number: F2



Photo: 20230130-083451-snap0001.jpg, 00:00:35
0.38m, Joint displaced medium

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
5

PLR Suffix :



Photo: 20230130-083451-snap0002.jpg, 00:00:47
0.38m, Cracks multiple at joint from/at 07 o'clock to 02 o'clock



Photo: 20230130-083451-snap0003.jpg, 00:01:17
0.91m, Line deviates left Remarks: DROPPING INTO PIPE RUNNING FROM
MANHOLE F1

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
5

PLR Suffix :



Photo: 20230130-083451-snap0004.jpg, 00:01:36
1.52m, Size changes new size(s) 150 mm high 150 mm wide



Photo: 20230130-083451-snap0005.jpg, 00:01:56
2.47m, Line deviates left

Place :

A1 DRAINAGE
ROYSTON AVENUE
EASTLEIGH
Tel: 02380 610413
Fax:

Email: a1drainagesouth@yahoo.com

Inspection pictures

Place :
EASTLEIGH

Road :
143 - 145 PASSFIELD AVENUE

Date :
30/01/2023

Section number :
5

PLR Suffix :



Photo: 20230130-083451-snap0006.jpg, 00:02:06

3.08m, Finish node type manhole reference number: DSTREAM INTO F3 MAIN

SEWER Remarks: LOCATED IN GARDEN OF NEIGHBOUR. UNABLE TO LOCATE