

Hound Manor
Tree works by priority, Sept 2024

Tree no.	Species	Location	Preliminary Recommendations	Reason	Priority rating	Notes
T1	Wych elm	Road frontage	Fell	Highway safty	1	Check ownership.
G3	Elm	Road frontage	Fell.	Highway safty	1	Check ownership.
T4	Sweet chestnut	Road frontage, c. 2-2.5m behind back edge of footway.	Fell.	Highway safty	1	
G5	Mixed species.	Along frontage to Hound Road	Lift to 3.0m and clear lamp columns 6 and 7 and signs by minimum 1m .	Highway safty	1	
G15	Sycamore, holly	South and southeast corner of building	Crown lift lower branches growing towards building to 4.5m taking small diameter laterals back to main stem. Max cut size 60mm diameter. Proximity prune remaining branches to clear building by minimum 2.0m	To avoid damage to property	1	
G20	Robinia x 2	NE corner of Manor, north sode of drive	Proximity prune to clear 2.0 to 2.5m to good pruning points	To avoid damage to property	1	To avoid damage to roof and gutter

Hound Manor
Tree works by priority, Sept 2024

Tree no.	Species	Location	Preliminary Recommendations	Reason	Priority rating	Notes
T6	Sweet Chestnut	North side of drive, west end	Sever ivy. Remove surrounding vegetation for minimum 1m to allow further investigation. Commission residrill or picus to inform internal investigation.	Safety and access	2	
T7	Monkey puzzle	North side of front lawn	Deadwood on south side. Clear vegetation on south side for 1m to allow further visual check.	Exempt	2	
T9	Sweet chestnut	Between two lawns	Trim epicormic growth from base to 1.5m above ground level. Restrict dumping of grass cuttings near this tree: find an alternative location away from important trees.	Access, to manage epicormic basal growth and to reduce likelihood of harm from leachate	2	
T10	Sweet chestnut	Between two lawns, south of T9	Trim epicormic growth from base to 1.5m above ground level. Restrict dumping of grass cuttings near this tree, find an alternative location away from important trees.	To manage epicormic basal growth and reduce likelihood of harm from leachate	2	
T16	Sycamore	Self-set by garage wall	Fell to near ground level. Treat stump with herbicide to control regrowth	To remove potential for damage to building	2	
T17	Sycamore	In group of 3 with holly west of main car park	Fell	Basal decay = foreseeable failure	2	Check ownership.
G19	Sycamore, laurel	Along west exit drive	Lift to 4.5m for access.	To be able to use/maintain lawn	2	
T11	Robinia	South side of drive, east end	Sever ivy. Prune to clear building by 2.0m.	To avoid damage to property	2	

Hound Manor
Tree works by priority, Sept 2024

Tree no.	Species	Location	Preliminary Recommendations	Reason	Priority rating	Notes
G8	Laurel	North side of east lawn	Lift to 3.5m above ground level	To be able to use/maintain lawn	3	
G13	Sycamore	East side of Manor	Lift to 4.0m for access. Remove hanger while other works being done.	Access	3	
T18	Bay	North of drive	Reduce in height to 2-2.5m and maintain from there.	Bring to a more manageable height.	3	Not a safety issue, just to bring back into appropriate form for setting