

## JR1-2396 Vistry Gateway Development


**Title:** Tree protection fencing audit

Boorley Park Local Centre (Conditions 6) - DC/23/95019

**Location:** Winchester Rd, Botley, SO32 2UA

**Month of inspection:** September 2024

**Report produced by:** Mavin Sarai (Jackson Rowe Associates Limited)



|                                       |                                                                                                                     |            |           |            |                                                                                                                                   |
|---------------------------------------|---------------------------------------------------------------------------------------------------------------------|------------|-----------|------------|-----------------------------------------------------------------------------------------------------------------------------------|
| JR1-2396 - Vistry Gateway Development |                                                                                                                     |            |           |            |                                                                                                                                   |
|                                       |                                                                                                                     |            |           |            |                                                                                                                                   |
| <b>Nr.</b>                            | <b>Question</b>                                                                                                     | <b>Yes</b> | <b>No</b> | <b>N/A</b> | <b>Comments/proposed action(s)</b>                                                                                                |
| 1                                     | Were all the proposed action(s) from the previous audit addressed                                                   | ✓          |           |            | As agreed with EBC, Arborcall have removed approx. 52 nr fence panels (images 1-6). Fencing adjacent to live site remains insitu. |
| 2                                     | Are all the fence panels erected                                                                                    | ✓          |           |            |                                                                                                                                   |
| 3                                     | Are all the fencing panels fixed with coupers with nuts internally to the fencing                                   | ✓          |           |            |                                                                                                                                   |
| 4                                     | Are all the feet and stabilising bars properly installed                                                            | ✓          |           |            |                                                                                                                                   |
| 5                                     | Are sand bags installed on top of the feet or are the feet pinned to the ground                                     | ✓          |           |            |                                                                                                                                   |
| 6                                     | Are signs installed on the fencing panels to inform site staff of their responsibilities around the protected areas | ✓          |           |            |                                                                                                                                   |
| 7                                     | Are any additional fencing panels required?                                                                         |            | ✓         |            |                                                                                                                                   |

**Figure 3 – JRA fencing survey**



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6



Image 7



Image 8



Image 9



Image 10



Image 12



Image 13



Image 14




Image 15



Image 15