CRACK MONITORING

for Subsidence Management Services

23 The Drove, Horton Heath, Eastleigh, Hants, SO50 7NX

Client:	Subsidence Management Services
Client Contact:	Peter Moore
Claim Number:	09BHI040652
Client Reference:	IFS-AVI-SUB-15-0056124
Policy Holder:	Mr & Mrs Kieron Johnson
Report Date:	22 January 2016
Our Ref:	M5477

SubsNetUK

SubsNetUK

Crack Monitoring Readings

The following table shows the reading levels of the Crack Monitoring Stations.

Date	A=B (H)	B=C (D)	A=C (V)(C)	Crack Width
C1 - INT - FF rear RH bedroom - LHS of window				
9 April 2015	75.48	105.98	71.84	0.60 - 0.60
10 June 2015	75.57	106.02	71.87	
19 August 2015	75.86	106.25	71.82	1.20 - 1.10
21 October 2015	75.19	106.11	71.86	0.70
20 January 2016	75.38	106.10	71.80	
Date	**A=B (H)**	**B=C (D)**	**A=C (V)**	**Crack Width**
C2 - INT - Lounge under window				
9 April 2015	68.78			0.30
10 June 2015	68.78			
19 August 2015	68.56			0.10
21 October 2015	68.79			0.10
20 January 2016	68.71			
Date	**A=B (H)**	**B=C (D)**	**A=C (V)**	**Crack Width**
C3 - INT - Lounge LHS of window (as viewed internally)				
9 April 2015	69.95			0.50
10 June 2015	70.04			
19 August 2015	70.82			1.50
21 October 2015	70.33			1.00
20 January 2016	69.96			0.90

Crack Monitoring Difference Graphs

The following graphs display the progressive movement that each Crack Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



C2 - INT - Lounge under window



C3 - INT - Lounge LHS of window (as viewed internally)



SubsNetUK