


Looking at the plans, it would appear that there would be an adequate 6.0m turning circle both directly adjacent to the property, and also a secondary option to the front of the property, though plans do not make clear if this will be driveway (hard surfacing) or front garden (landscaping).



As such, in terms of usability, I would have no concerns.