

A.J.MONK CONSULTING Tel:07309749629	TREE SURVEY SCHEDULE							
	Client:	Jason Lomas				Site:	Old Oak Farm, Winchester Road, Fair Oak SO50 7HD	
	Date:	Updated 28th April 2023				Consultant:	Alexa Monk <i>Tech Cert (Arbor A), NCH Arb</i>	
	Tagged:	No				Weather:	Cloudy & dry	

Notes:-

1. It may be advised that some trees should have the ivy removed to enable a re-survey to be carried out. This would also alleviate the tree from becoming suppressed; carrying additional weight that increases the chance of windthrow due to a larger dense crown area; and only receiving restricted light. Unless otherwise stated, in order to prevent regrowth, it is only necessary to remove a 300mm section of ivy and clear around the base.
2. It may be advised that it was only possible to estimate the diameter of some trees because of ivy smothering, dense vegetation, or trees located off-site with no access.
3. The estimated remaining contribution in years, and the tree grading category have been calculated for the current situation and may alter where further investigation works are advised.
4. Some trees or groups may have been given an interim grade. The reason for the interim grading is addressed in the timescales given as this may have a bearing on health and safety and/or any development proposals.
5. Tree Groups have been assessed with estimated and representative data.
6. This is not a Tree Works Schedule. Any preliminary management recommendations are listed in the interests of health and safety and should be carried out by a prudent tree owner.
7. Any management recommendations are suggested for reasons of health and safety only, regardless of development proposals at this stage. However, the defects requiring remedial tree surgery are by their very nature potential wildlife habitats, including protected species which needs consideration prior to any tree surgery works commencing.

Tree No	Species	H't (m)	Single/ Multi-Stemmed (S or MS)	Stem Diam (mm)	Branch Spread (m)				H't of Crown AGL (m)				Age	Physio-logical Condition	Structural Condition and Relevant Comments	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
					N	E	S	W	N	E	S	W						
1	Silver Birch	8	MS	160 160	2.0	1.0	2.0	2.5	2.0	2.0	2.0	2.0	SM	Good	Fair, bifurcated at ground level. Crown shape distorted due to group pressure	None required at time of survey	20+	C1
2	Silver Birch	8	MS	140 130	2.0	2.5	2.0	1.0	2.0	2.0	2.0	2.0	SM	Good	Fair, bifurcated at ground level. Crown shape distorted due to group pressure. Bark wound at base of stem	None required at time of survey	10+	C1
3	Goat Willow	3.5	MS	110 150	2.0	2.0	2.5	2.0	1.5	1.5	1.5	1.5	SM	Good	Fair, bifurcated at 1.2m above ground level. Crossing branches	None required at time of survey	20+	C1
4	Goat Willow	3	MS	80 x8	3.0	3.0	2.0	2.0	0.0	0.0	0.0	0.0	SM	Good	Fair, multi stemmed at ground level. Low hanging branches	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi-Stemmed (S or MS)	Stem Diam (mm)	Branch Spread (m)				H't of Crown AGL (m)				Age	Physio-logical Condition	Structural Condition and Relevant Comments	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
					N	E	S	W	N	E	S	W						
5	Pedunculate Oak	16	S	Est 760	10.0	11.0	9.0	10.0	7.0	3.0	5.0	2.0	M	Good	Good, off site tree. Estimated data due to no access. Multi stemmed at 4m above ground level with minor dead wood in crown	None required at time of survey	40+	B1
6	Goat Willow	9	S	440	5.0	4.0	1.0	6.0	4.0	5.0	4.0	3.0	M	Fair	Fair, ditch line tree. Bifurcated at 2.5m above ground level. Crown shape distorted due to group pressure. Minor dead wood in crown	None required at time of survey	20+	C1
7	Pedunculate Oak	13	S	740	4.0	6.0	4.0	6.0	6.0	4.0	6.0	3.0	M	Good	Good, ditch line tree. Multi stemmed at 4.5m above ground level. Dead wood in crown (low risk)	None required at time of survey	40+	B1
8	Common Hawthorn	4	S	210	2.0	2.0	2.0	2.0	2.0	2.0	2.0	2.0	SM	Good	Fair, ditch line tree. Ivy on trunk. Crossing branches	None required at time of survey	20+	C1
9	Goat Willow	13	MS	270 170 370	6.0	1.0	6.0	7.0	4.0	7.0	5.0	3.0	EM	Good	Fair, trifurcated at ground level. Ditch line tree. Ivy on trunks. Crown shape distorted due to group pressure. Minor dead wood in crown with dead wood hanger still attached and low risk.	None required at time of survey	20+	C1
10	Goat Willow	8	MS	240 190	3.0	2.0	3.0	6.0	4.0	6.0	4.0	1.0	SM	Fair	Fair, ditch line tree. Ivy on trunk. Bifurcated at 1.2m above ground level. Crown shape distorted due to group pressure. Crown bias to west	None required at time of survey	20+	C1

Tree No	Species	H't (m)	Single/ Multi-Stemmed (S or MS)	Stem Diam (mm)	Branch Spread (m)				H't of Crown AGL (m)				Age	Physio-logical Condition	Structural Condition and Relevant Comments	Preliminary Management Recommendations	Est. Rem. Contrib. (Yrs)	Cat
					N	E	S	W	N	E	S	W						
11	Goat Willow	8	MS	250 350	2.0	4.0	3.0	6.0	3.0	3.0	5.0	0.5	EM	Fair	Fair, bifurcated at 1.3m above ground level. Ivy on trunks. Ditch line tree. Crown shape distorted due to group pressure	None required at time of survey	20+	C1
12	Pedunculate Oak	16	S	Est 800	10.0	7.0	8.0	9.0	3.0	2.0	4.0	2.0	M	Good	Estimated data due to limited access. Grows on bank. Minor dead wood in crown. Good shape and form.	None required at time of survey	40+	A1
13	Goat Willow	3	MS	80 x9	3.0	4.0	3.0	4.0	1.0	1.0	1.0	1.0	SM	Fair	Fair, multi stmmed at ground level	None required at time of survey	20+	C1
H1	Leyland Cypress	3	S	120	-	-	-	-	-	-	-	-	SM	Good	Fair, partly maintained deviding hedge	None required at time of survey	10+	C2
H2	Leyland Cypress Hawthorn	4	S	90	-	-	-	-	-	-	-	-	SM	Good	Good in sire deviding hedge. Sporadic growth on south boundary	None required at time of survey	20+	C2
H3	Blackthorn Hawthorn Goat Willow	2.5	S	80	-	-	-	-	-	-	-	-	SM	Good	Fair, roadside boundary hedge. Low hanging branches. Crossing branches. Provides good visual separation to and from site.	None required at time of survey	20+	C2