

From: [Fiona Goode](#)
To: enquiries@raymondbrown.co.uk
Subject: Technical Resource Consultation - Boorley Green, Hampshire
Date: 23 June 2025 12:57:00
Attachments: [GE23078 - Site Location.pdf](#)
[GE23094 - Site Location Plan.pdf](#)

Hello,

We are currently writing a couple of Mineral Resource Assessments for two separate sites both located in Boorley Green, Hampshire (Maddoxford Farm grid ref 451533, 114552 and Holly Tree Farm grid ref 451454, 114184) as the Hampshire Minerals and Waste Local Plan has defined the sites to be within a mineral safeguarding area. I have attached site boundary plans for each of the sites.

As such, we need to consult with mineral operators who, more readily understand the economic and technical issues relevant to mineral extraction, to confirm with industry if the anticipated underlying ground conditions of the site; sand and gravel of the River Terrace Deposits in the eastern portion of both sites, overlying sand, silt and clay of the Wittering Formation, and sand silt and clay of the London Clay Formation in the northern portion of the Maddoxford Farm site only, is a commercially viable resource.

We just need a quick response to: Do you feel this is a viable mineral resource?

If you have any queries, please do not hesitate to get in touch,

Thanks in advance for your help,

From: [Fiona Goode](#)
To: restore.south@tarmac.com
Subject: Technical Resource Consultation - Boorley Green, Hampshire
Date: 23 June 2025 12:57:00
Attachments: [GE23078 - Site Location.pdf](#)
[GE23094 - Site Location Plan.pdf](#)

Hello,

We are currently writing a couple of Mineral Resource Assessments for two separate sites both located in Boorley Green, Hampshire (Maddoxford Farm grid ref 451533, 114552 and Holly Tree Farm grid ref 451454, 114184) as the Hampshire Minerals and Waste Local Plan has defined the sites to be within a mineral safeguarding area. I have attached site boundary plans for each of the sites.

As such, we need to consult with mineral operators who, more readily understand the economic and technical issues relevant to mineral extraction, to confirm with industry if the anticipated underlying ground conditions of the site; sand and gravel of the River Terrace Deposits in the eastern portion of both sites, overlying sand, silt and clay of the Wittering Formation, and sand silt and clay of the London Clay Formation in the northern portion of the Maddoxford Farm site only, is a commercially viable resource.

We just need a quick response to: Do you feel this is a viable mineral resource?

If you have any queries, please do not hesitate to get in touch,

Thanks in advance for your help,