

It is good to see the existing sash boxes are to be retained and repaired as necessary with just new hardwood sashes installed within them with thin double glazing to improve the thermal performance.

The only observation I would make is that I think the rear elevation would look better if the two windows on the right hand side did not have the vents which dates them to the last century.

No objection.