

T1 - Silver Birch. – Fell. In acute decline, roots breaching the drains.



