

Report produced by: Mavin Sarai (Jackson Rowe Associates Limited)

JR1-2396 - Vistry Gateway Development				
Nr. Question	Yes	No	N/A	Comments/proposed action(s)
1 Were all the proposed action(s) from the previous audit addressed	✓			Arbourcall attended site and completed actions from previous audit. See tree remedial actions 1, 2 and 3
2 Are all the fence panels erected	✓			
3 Are all the fencing panels fixed with coupers with nuts internally to the fencing	✓			
4 Are all the feet and stabilising bars properly installed	✓			
5 Are sand bags installed on top of the feet or are the feet pinned to the ground	✓			
6 Are signs installed on the fencing panels to inform site staff of their responsibilities around the protected areas	✓			
7 Are any additional fencing panels required?	✓			

Figure 3 – JRA fencing survey

TREE REMEDIAL ACTIONS - 1

BEFORE



AFTER



Fence panels reinstated and positioned up-right.

TREE REMEDIAL ACTIONS - 2

BEFORE



AFTER



Fence panels reinstated as per original instruction including addition of feet as means of extra support.

TREE REMEDIAL ACTIONS - 3

BEFORE



Approx 2nr fence panels added to existing fencing to secure till the end of road. Additionally, feet added as means of extra support.

AFTER





Image 1



Image 2



Image 3



Image 4



Image 5



Image 6



Image 7



Image 8



Image 9



Image 10



Image 11



Image 12



Image 13