

SCHEDULE OF TREE WORKS

Ref no	Species	Works to be carried out
Areas of scrub/thicket vegetation illustrated with red hexagonal hatching in the Arboricultural Implications Assessment plan and within the footprints of proposed structures and earthworks.	Mixed woody and herbaceous plants	Fell to ground level. Stumps to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
Areas of scrub/thicket vegetation illustrated with red hexagonal hatching in the Arboricultural Implications Assessment plan and outside the footprints of proposed structures and earthworks.	Mixed woody and herbaceous plants	Coppice. Stumps to be left in place and given the chance to regrow.

Ref no	Species	Works to be carried out
3 sections of hedge illustrated with red crown margins in the Arboricultural Implications Assessment plan	Mixed native hedge plant	Fell to ground level. Stumps to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T2	Norway Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T3	Ash	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T4	Elm	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T5	Norway Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T29	Common Oak	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T30	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T31	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T32	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T33	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T34	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T35	Norway Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).

Ref no	Species	Works to be carried out
T36	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T37	Scots Pine	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T38	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T39	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T40	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T41	Scots Pine	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T42	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T43	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T44	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T45	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T46	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T47	Ash	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T48	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T49	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).

Ref no	Species	Works to be carried out
T50	Norway Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T51	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T52	Ash	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T53	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T54	Norway Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T55	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T56	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T57	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T58	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T59	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T60	Field Maple	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T61	Common Oak	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T82	Common Oak	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T83	Common Oak	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).

Ref no	Species	Works to be carried out
T84	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
Dead tree near T84	Oak	Not numbered. Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T85	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
Moribund tree near T85	Alder	Not Numbered. Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T87	Alder	Coppice. Stump to be left in place and given the chance to regrow.
T88	Alder	Coppice. Stump to be left in place and given the chance to regrow.
T89	Alder	Coppice. Stump to be left in place and given the chance to regrow.
T90	Alder	Coppice. Stump to be left in place and given the chance to regrow.
T91	Crack Willow	Coppice. Stump to be left in place and given the chance to regrow.
T92	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T93	Crack Willow	Coppice. Stump to be left in place and given the chance to regrow.
T94	Willow	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T95	Willow	Coppice. Stump to be left in place and given the chance to regrow.
T96	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).

Ref no	Species	Works to be carried out
T97	Alder	Coppice. Stump to be left in place and given the chance to regrow.
T98	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T99	Alder	Coppice. Stump to be left in place and given the chance to regrow.
T100	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T101	Alder	Coppice. Stump to be left in place and given the chance to regrow.
T102	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T103	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T104	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T109	Crack Willow	Coppice. Stump to be left in place and given the chance to regrow.
T110	Crack Willow	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T122	Alder	Coppice. Stump to be left in place and given the chance to regrow.
T142	Crack Willow	Coppice. Stump to be left in place and given the chance to regrow.
T146	Willow	Coppice. Stump to be left in place and given the chance to regrow.
T149	Willow	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).

Ref no	Species	Works to be carried out
T150	Common Oak	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T151	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T153	Alder	Coppice. Stump to be left in place and given the chance to regrow.
T154	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T155	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T156	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T157	Alder	Coppice. Stump to be left in place and given the chance to regrow.
T158	Ash	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T159	Ash	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T160	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T161	Ash	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T162	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T163	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T164	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).

Ref no	Species	Works to be carried out
T165	Hawthorn	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T166	Ash	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T167	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T167A	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T168	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T169	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T170	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T171	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T172	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T173	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T174	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T175	Willow	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T176	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T177	Ash	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).

Ref no	Species	Works to be carried out
T178	Alder	Coppice. Stump to be left in place and given the chance to regrow.
T179	Ash	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T180	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T181	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T182	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T183	Willow	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T184	Willow	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T187	Common Oak	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T188	Common Oak	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T189	Ash	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T190	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T191	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T192	Common Oak	Coppice. Stump to be left in place and given the chance to regrow.
T193	Common Oak	Coppice. Stump to be left in place and given the chance to regrow.

Ref no	Species	Works to be carried out
T194	Common Oak	Coppice. Stump to be left in place and given the chance to regrow.
T195	Common Oak	Coppice. Stump to be left in place and given the chance to regrow.
T203	Common Oak	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
T442	Alder	Fell to ground level. Stump to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
G1	Mixed, but predominantly Prunus and Field Maple, and including tree no's. T30 to T47 inclusive.	Fell to ground level. Stumps to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
G2	Mixed, but predominantly Prunus and Field Maple Occasional Hawthorn and Ash, and including tree no's. T48 to T60 inclusive.	Fell to ground level. Stumps to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
G4	Alder	Fell to ground level. Stumps to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).
G5 part only	Predominantly Alder with Crack Willow, Ash and Common Oak, and including tree nos. T111 to T222 inclusive.	Fell to ground level part of the group as denoted by individual trees with red crown margins in the Arboricultural Implications Assessment plan, and denoted by red hexagonal hatching in the Arboricultural Implication Assessment plan. Stumps to be grubbed out after the tree protection barriers have been erected and by the construction contractor(s).

Appendix 9 References

- | | | |
|---------------------------|---|--|
| BS5837:2012 | = | British Standard 5837:2012 'Trees in relation to design, demolition and construction – Recommendations'. |
| BS3998:2010 | = | British Standard 3998:2010 'Tree work – Recommendations'. |
| Helliwell 2004 | = | Helliwell, R. (2004) Short Paper: A Discussion of the Failure of Weak Forks. <i>The Arboricultural Journal</i> . 27:3, pp245-249. |
| Mattheck & Breloer = 1994 | = | Mattheck, C., Breloer, H. (1994) <i>The Body Language of Trees: A Handbook for Failure Analysis</i> . In: Department of the Environment; Lonsdale, D. (Ed) Research for Amenity Trees. HMSO, England. pp52-57. |