

JR1-2396 Vistry Gateway Development


Title: Tree protection fencing audit

Boorley Park Local Centre (Conditions 6) - DC/23/95019

Location: Winchester Rd, Botley, SO32 2UA

Month of inspection: February 2025

Report produced by: Mavin Sarai (Jackson Rowe Associates Limited)



JR1-2396 - Vistry Gateway Development				
Nr.	Question	Yes	No	N/A
1	Were all the proposed action(s) from the previous audit addressed	✓		
2	Are all the fence panels erected	✓		
3	Are all the fencing panels fixed with coupers with nuts internally to the fencing		✓	JR have reviewed this with Arborcall who advised that due to the construction completion within this area the fencing can now be removed from March 2025 rather than be replaced or repaired.
4	Are all the feet and stabilising bars properly installed	✓		
5	Are sand bags installed on top of the feet or are the feet pinned to the ground	✓		
6	Are signs installed on the fencing panels to inform site staff of their responsibilities around the protected areas	✓		
7	Are any additional fencing panels required?	✓		Damaged fence panels - JR have reviewed this with Arborcall who advised that due to the construction completion within this area the fencing can now be removed from March 2025 rather than be replaced or repaired.

Figure 3 – JRA fencing survey



Image 1



Image 2



Image 3



Image 4



Image 5



Image 6



Image 7



Image 8



Image 9



Image 10