Sheet A

N



Anchorage Field is approx 3 ft higher than Fairport Cottage land.

Pine tree which is the subject of this application

Sheet B

FROM FAIRPORT COTTAGE





severely damaged branches

remnant of tree brought down by gales

THE PINE TREE HAS BEEN BADLY DAMAGED IN THE STRONG COASTAL GALES WHICH BROUGHT DOWN THE TREE NEXT TO IT, CUTTING THE POWER SUPPLY TO LANDS END ROAD.

close proximity to Fairport Cottage.

Sheet C



ROOT DAMAGE TO THE TARMAC AT THE TOP OF FAIRPORT COTTAGE DRIVE