

Fig. 1 84 Thornbury Wood – bottom of garden facing West, showing trees on Section 7 plan.




Fig 2 View of trees from neighbouring 82 Thornbury Wood facing South.

Picture taken in spring before foliage appeared.

It is clear from this picture that the main boughs on the west facing side of SB1 have been removed in the past, so that the tree is unbalanced with all the major lower boughs on the east side