Matt Godwin
Director
Titchfield Tree Services
18 Little Park Farm Road
Fareham
PO155TD
01489571103



CLIENT NAME	CONTACT NUMBER	QUOTATION DATE	JOB NUMBER
Mr Misslebrook	07900492171 teamsteve@hotmail.co.uk	21/1/16	J16023

SITE ADDRESS	INSPECTED BY	Matt Godwin	
Stable Cottage School Road Bursledon SO31 8BW	SITE PLAN ATTACHED		No
	COMMENCEMENT DATE	TBA	

JOB DESCRIPTION		
TREE NUMBER (price ex. VAT @20%)	SPECIES/ location	WORK REQUIRED
T2	Turkey Oak in rear garden.	Crown lift to 8m from ground level with the removal of pendula branches no greater than 75mm in diameter. Crown thin by 25% of oval crown by removing epicormics only. Shorten over extended lateral branch work by no more than 3m to keep a balanced crown. Remove all major deadwood.
ST1	Chestnut stump	Grind stump to 300mm below ground level.
T3/T4	Portuguese Laurel	Windblown. Fell to 3m from ground level. Retain timber on site. Remove brash.
G1	Laurel	Fell to create a path through woodland.
T3/T4/G1		
G2	Mixed shrubs	Fell all Laurel to just above ground level including overgrown shrubs retaining specimen trees (Hornbeam/Yew/Bay) With a view to crown lift to 3.5m. Grind stumps to 300mm below ground level. Fell heavily weighted tree over highway due to poor form.


School Rd
T3/T4
T2
G2
G1