TREES

| | |
|---|---|
| A | Ash |
| AL | Alder |
| AP | Apple |
| B | Beech |
| C | Cedar |
| CB | Copper Beech |
| CH | Cherry |
| CY | Cypress |
| E | Elm |
| EL | Elder |
| EU | Eucalyptus |
| F | Fir |
| FM | Field Maple |
| FR | Fruit |
| HZ | Hazel |
| HC | Horse Chestnut |
| HO | Holm Oak |
| HW | Hawthorn |
| HY | Holly |
| IBT | Indian Bean Tree |
| LB | Laburnum |
| LI | Lime |
| LO | Locust Tree |
| LR | Laurel |
| M | Maple |
| MG | Magnolia |
| OK | Oak |
| P | Pine |
| PA | Palm |
| PL | Plane |
| PM | Plum |
| PO | Poplar |
| PP | Pissardii Plum |
| PR | Pear |
| R | Redwood |
| RD | Red Oak |
| RH | Rhododendron |
| RO | Rowan |
| SB | Silver Birch |
| SC | Sweet Chestnut |
| SP | Scots Pine |
| SU | Spruce |
| SY | Sycamore |
| U | Unidentified |
| W | Willow |
| WN | Walnut |
| Y | Yew |

Species / Dia / Spread (max) / Ht
e.g. OK / 0.6 / 8 / 15

KEY

| | |
|---|---|
| BT | British Telecom |
| BOL | Bollard |
| CB | Control Box |
| CL | Cover Level |
| CTV | Cable Television |
| EL | Level |
| EP | Electricity Pole |
| FH | Fire Hydrant |
| GSV | Gas Stop Valve |
| HT | Height |
| HVC | High Voltage Cable |
| IC | Inspection Cover |
| IL | Invert Level |
| LP | Lamp Post |
| MH | Man-Hole |
| MKR | Marker |
| MW | Monitoring Well |
| O/H | Overhead |
| G | Road Gully |
| PB | Post Box |
| PC | Pram Crossing |
| RNP | Road Name Plate |
| RS | Road Sign |
| S/A | Soakaway |
| SY | Stay / Strut |
| SV | Stop Valve (Unidentified) |
| TB | Telecoms Box |
| TC | Telegram |
| TH | Trial Hole |
| TL | Traffic Light |
| TP | Telegraph Pole |
| UTL | Unable to Lift |
| VP | Vent pipe |
| WM | Water Meter |
| WSV | Water Stop Valve |

FENCES

| | |
|---|---|
| BWF | Barbed Wire Fence |
| CBF | Closed Board Fence |
| CF | Concrete Post |
| CPF | Chestnut Paling Fence |
| CWF | Chicken Wire Fence |
| IRF | Iron Railing Fence |
| PKF | Picket Fence |
| PRF | Post & Rail Fence |
| PWF | Post & Wire Fence |
| SCF | Security Fence |
| SP | Steel Post |
| WMF | Wire Mesh Fence |
| WPF | Wood Panel Fence |

SURVEY STATION INFORMATION

| STATION | EASTING | NORTHING | LEVEL | TYPE |
|---|---|---|---|---|
| B1 | 447636.305 | 109758.678 | 35.433 | NAIL |
| B2 | 447620.901 | 109695.006 | 35.037 | NAIL |
| B3 | 447602.620 | 109619.098 | 34.237 | NAIL |
| B4 | 447602.512 | 109788.902 | 35.884 | NAIL |
| B7 | 447611.068 | 109609.082 | 34.255 | NAIL |
| B8 | 447603.760 | 109538.282 | 33.597 | NAIL |
| B13 | 447537.766 | 109617.225 | 34.572 | NAIL |
| B14 | 447567.822 | 109640.191 | 34.586 | NAIL |
| B20 | 447530.956 | 109625.399 | 34.516 | NAIL |

General Notes

The survey grid has been related to OS National Grid using a flat earth projection and metric scale factor of 1, centred on Station B3.
Levels are related to OS datum determined from the National GPS Network using OSGM02.

No assumptions should be made regarding the interconnection of manholes. Drainage details have been obtained from surface inspection and should be verified if of critical importance.

Service Tracing Notes

The oil pipeline has been traced using electromagnetic detection only and it should be noted that record drawings were not available at the time of survey. The results from this type of survey are not infallible and it is strongly advised that the results should be verified by a secondary method such as ground penetrating radar or trial excavations. Where obtainable, depths shown are approximate and are to top of service. No other services have been surveyed.


Geomatic Surveyors

siteline

Unit E, Woodside
34 Parham Drive
Eastleigh
SO50 4NU

t: 023 8081 1081
f: 023 8081 1012
w: siteline.co.uk


| | |
|---|---|
| BARRATT DAVID WILSON HOMES | Client |
| BERRY FARM BURSLEDON HAMPSHIRE | Contract |
| SITE SURVEY | Title |
| 36BZ001 | Drawing No. |
| JULY 2013 | Date |
| 1:200 (OVERSIZE) | Scale |
| ST / IA | Surveyor |