

Figure 20 - Representative viewpoints 1-4



VP 1: On site boundary. Looking north from entrance to Brookfield off Providence Hill; view across area of site immediately adjacent to road. Levels, intervening vegetation and built form screen majority of site from view, however ground plane of site not visible. Bursledon Windmill is visible in view; this is the 'important view' as identified in the Bursledon Windmill Conservation Area Management Plan.



VP 2: 20m from site boundary. Looking north from south side of Providence Hill. Views into site are screened by intervening vegetation, tree line along roadside and built form of Brookfield. Upper sections of mature trees along stream to north of site are visible. Ground plane of site not visible.



VP 3: 50m from site boundary. Looking north west from Providence Hill. Site screened by intervening tree line along roadside and built form of Brookfield.



VP 4: 230m from site boundary. Looking north west along Providence Hill. No view of site due to intervening vegetation and rising landform.

Figure 21 - Representative viewpoints 5-8




VP 5: 260m from site boundary. Looking north across Lowford from highest point of recreation ground. No view of site due to topography; site lies in valley and is screened by intervening built form and close intervening vegetation.



VP 6: 280m from site boundary. Looking north from Long Lane. No view of site due to intervening vegetation.



VP 7: 230m from site boundary. Looking north from footpath between Long Lane and The Grove. No view of site due to intervening vegetation and built form.



VP 8: 30m from site boundary. Looking north along footpath between Lionheart Way and Providence Hill. Glimpsed view of short section of site boundary along footpath only. No wider views of site due to intervening vegetation and built form.

Figure 22 - Photographic record of baseline conditions: Representative viewpoints 9-12



VP 9: 20m from site boundary. Looking south east along Providence Hill from pavement on southern side of Providence Hill. Views into site screened by vegetation but partial views of western area of site may be possible in winter without leaf cover (wide angle photo)



VP 10: 65m from site boundary. Looking south east along Providence Hill opposite Windmill Lane. No view of site due to intervening vegetation.



VP 11: 25m from site boundary. Looking south east across entrance to Goslings Turning on southern side of Windmill Lane. No view of site due to intervening vegetation along site boundary and residential properties.



VP 12: 100m from site boundary. Looking south from Bursledon Windmill. No view of site due to intervening vegetation and built form.

Figure 23 - Photographic record of baseline conditions: Representative viewpoints 13-15



VP 13: View from top of open space off Goslings Turning; views to existing residential properties at Brookfield (stitched panorama). Partial views of the site are possible through intervening vegetation.



VP 14: Looking south west from Dodwell Lane at entrance to the Moor House. No view of site due to landform and intervening vegetation.



VP 15: Looking west from bridge over M27 on Dodwell Lane. No view of site due to intervening vegetation.

Figure 24 - Photographic record of baseline conditions: Representative viewpoint 16



VP 16: Looking west from Dodwell Lane. No view of site due to intervening vegetation.