

Trees Consultation Response
Received 17/05/2023

H/23/95031 - 7 OAKHILL CLOSE, BURSLEDON

Arboricultural Documents

None

Comments

There are two oak trees within potential influencing distance to the structure – one to the east and one to the west. These trees are subject to a Tree Preservation Order.

The structure may be within the Root Protection Areas of these two trees and, thus, may have had a negative impact. However, without arboricultural information – tree survey and impact assessment – it is not possible to determine.

Therefore, we raise a holding objection and request arboricultural information. In addition, we would like a method statement detailing any remedial work, if it is deemed that there has been a negative impact.