



(04) Photo looking South from the bend within the Crowsport Estate at No.18's 2nd site and vehicle entrance, defined by double timber gates, due to be replaced or refurbished during the proposed works. In addition, this photo also highlights the nature of the front boundary treatment and the masking that this provides to the dwelling.



(05) Photo looking south from within that site at the Bungalow's existing front door and block paved approach, highlighting its white rendered material finish, with simple window opening character.



(06) Photo looking East from within the front “Courtyard Style Garden”, highlighting the form, material finish and simple character incorporated into the existing Bungalow’s composition.



(07) Photo looking South-West across the inner “Courtyard Style Garden” highlighting the material form of the Bungalow’s Western wing and the enclosed, private nature of the amenity space.



(08) Photo looking East from within the front “Courtyard Style Garden” at the side of the existing Double Garage, due to be demolished and reincorporated into the volume of the remodelled dwelling.



(09) Photo looking South-East at the side of the Bungalow’s Western wing, highlighting the general form and material character for this part of the property.