Bampton House

NOTES

1

Topographic Survey by Twenty 20 Surveys Ltd.
22 Pembroke Road Salisbury
Wiltshire
SP2 9DG

Surface water drainage leading to outfall into Monk's Brook. All as existing and to remain unchanged throughout and on completion of works.

Foul water drainage. Route within existing building and beyond not known.

Primmer Olds BAS
— Chartered Surveyors —
61 Cromwell Road
Southampton
Hampshire,SO15 2JE
Tel:023 8022 2292

Project Title:	Bampton House Chandler's Ford SO53 2TA		
Drawing Title:	Topographic Survey - Drainage Sketch		
Client	Rivendale Homes		
Dwg No:	21/70/006	Scale	1:50 @ A1
Drawn		Date	June 2022

All dimensions are in millimeters and are to be checked on site.
Contact Primmer Olds BAS with any queries and to report any discrepancies.