

Land to the Northwest of Boorley Green, SO32 2BX (Phase RM2)

DISCHARGE OF CONDITIONS

Introduction:

ACD have been instructed to produce a technote to address condition 6 of planning application RM/18/84466 and condition 8 of planning application X/19/84943, which both relate to confirmation of implementation of tree protection measures onsite.

Reference should be made to the following files:

- MILL22017-03 – Tree Protection Plan.
- MILL22017aia-ams – Arboricultural impact Assessment & Method Statement.
- Condition 6 of planning application RM/18/84466.
- Condition 8 of planning application X/19/84943.

Summary:

A site visit was conducted by ACD on 06.04.23 to assess the Tree Protection Fencing erected onsite at the development within the RM2 phase of the development.

The erected fencing was found to be of an adequate specification of wire-mesh 'heras' panels fixed to a sturdy scaffold frameworks and uprights throughout the development.

Photos below have been included to show adequate Tree Protection Fencing erected onsite for trees within the RM2 phase of the development.

Henry Pinn *L4 Arb (ABC)*
Senior Arboricultural Consultant

12/05/2023

Revision A – 30/05/2023 – Additional application/condition reference added



Figure 1: Photo Showing TPF around T7



Figure 2: Photo Showing TPF around T7



Figure 1: Photo Showing TPF around H8



Figure 4: Photo Showing TPF around H8



Figure 5: Photo Showing TPF around H7 & G9 leading into G10



Figure 6: Photo Showing TPF around G12 leading onto T8 and G11



Figure 7: Photo Showing No-dig pedestrian bridge for the Public Right of Way through G12



Figure 8: Photo Showing TPF around G12 (taken from within the Public Right of Way)



Figure 9: Photo Showing TPF around G12



Figure 10: Photo Showing TPF around H4 and H6 leading into G8



Figure 11: Photo Showing TPF around G14



Figure 12: Photo Showing TPF around T19