

Annex A 12.04.23



Facing from the beach up Beach Lane. Multiple pot holes and scarred surfaces.



Beach Lane facing the entrance to the beach. Google image August 2020. Very scarred and pot holed surface.



Beach Lane facing the entrance to the beach, close up. Google image August 2020. Very scarred and pot holed surface.



Beach Lane entrance to the beach. Google image August 2020. Very scarred and pot holed surface.