

LEVEL MONITORING

for Subsidence Management Services

19 Beechwood Rise, Southampton, Hampshire, SO18 3PW

Client:	Subsidence Management Services
Client Contact:	Richard Bryant
Claim Number:	4005487838
Client Reference:	IFS-ESU-SUB-22-0103393
Policy Holder:	Mrs Dawn Linington
Report Date:	1 November 2023
Our Ref:	M21957

Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	1	2	3	4	5	6	7	8	9	10
06/09/2023	10.0000	10.6591	10.3599	10.3666	10.3571	10.3641		10.6657	10.6631	10.6574
31/10/2023	10.0000	10.6592	10.3600	10.3662	10.3575	10.3714	10.3772	10.6685	10.6675	10.6614



Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

Site Visit Notes

Datum is level station 1, it has an assumed value of 10,0000m. No suitable secondary datum available. If this is not suitable, please advise if a deep datum is required. Relative Survey.