T88
T87
T21
T22
T23
Fallen dead Cherry
H20
G44
T52
G19
G19
T208
T207
T209
T210
T211
T212
T213
T214
T215
T216
T217
T218
T219
T220
T221
T222
T223
T224
T225
T226
T227
T228
T229
T230
T266
G100
G100
G100
G100
G17
G100
T267
G100
G100
G97
T50
T49
G18
G40
T206
T205
T204
T203
T202
H17
G95
T201
T200
T199
T198
T197
T196
T195
T194
G38
G94
H16
T48
H18
G39
T192
T191
T190
T189
T188
T187
G72
T109
T108
T110
T114
T115
T112
T113
T111
G72
G71
T186
T185
T184
T183
T182
G93
T181
T180
T179
T178
T177
T176
T175
T174
T173
T172
T171
T170
W3
W4
T57
T56
G45
T55
H26
H28
H27*
W5
*G90
H26
T54 (collapsed)
H30
*G90
*G90
Fallen Crack Willow
T58
G48
H32
H31
H28
G46
G47
G57*
H29
H24
H23
1
2
3
4
5
6
7
8
0
25m
North

Tyler Grange

Head Office: Marsden Estate, Rendcomb,
Cirencester, Gloucestershire, GL7 7EX

E:info@tylergrange.co.uk
W: www.tylergrange.co.uk

Key:

- Site Boundary
- Category A - Trees of High Quality and Value
- Category B - Trees of Moderate Quality and Value
- Category C - Trees of Low Quality and Value
- Category U - Trees Recommended for Removal
- Approximate Extent of BS5837 Calculated Root Protection Areas (RPAs)
- Veteran Tree and Ancient Woodland Buffer Zones
- BS 5837 Calculated Tree Shadow Constraints
- Approximate Locations of the Trees Covered by a TPO

*Denotes trees and groups not identified on topographical. Locations approximated using measurements taken on site.

This document should not be relied on or used in circumstances other than those for which it was prepared and for which Tyler Grange was appointed.

Tyler Grange accepts no responsibility for this document to any other party other than the person by whom it was appointed.

Tyler Grange Group Limited
Copyright © Tyler Grange Group Limited 2023

Rev	Description	Date
J	Additional tree survey (Fir Tree Lane)	23.02.2023
I	Additional tree survey	17.11.2022

Project title
Land at Horton Heath

Drawing title
Tree Constraints Plan - Sheet 3 of 8

Scale 1:750 @ A0
Date 23.02.2023
Drawn JP/LB
Checked JP

Drawing number
11705_P02

Revision
J