

Boorley Gardens, Development Tree Protection Report

Title: Tree Protection Report


Site Address: Boorley Gardens; Off Winchester Road, Botley SO32 2UA

Month of Inspection: February 2026

Inspection Carried out by: Matthew Rolls – Assistant Quantity Surveyor

Version: 1

Boorley Gardens, Development Tree Protection Report



www.thrivearchitects.co.uk

Copyright © 2014 Thrive Architects Ltd. All rights reserved. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, recording, or by any information storage or retrieval system, without prior written permission from Thrive Architects Ltd.

No.	Description	Date	By	Chk
11	Final Report	2014/01	TH	TH
12	Final Report	2014/01	TH	TH
13	Final Report	2014/01	TH	TH
14	Final Report	2014/01	TH	TH
15	Final Report	2014/01	TH	TH

Project	Boorley Gardens
Client	Boorley Gardens
Drawn	TH
Checked	TH
Scale	1:1000
Date	2014/01
Drawn by	TH
Checked by	TH
Scale	1:1000
Date	2014/01



Boorley Gardens, Development Tree Protection Report



Figure 1

Boorley Gardens, Development Tree Protection Report



Figure 2

Boorley Gardens, Development Tree Protection Report



Figure 3

Boorley Gardens, Development Tree Protection Report



Figure 3

Boorley Gardens, Development Tree Protection Report



Figure 5

Boorley Gardens, Development Tree Protection Report



Figure 6

Boorley Gardens, Development Tree Protection Report



Figure 7

Boorley Gardens, Development Tree Protection Report



Figure 8

Boorley Gardens, Development Tree Protection Report



Figure 9

Boorley Gardens, Development Tree Protection Report



Figure 10

Boorley Gardens, Development Tree Protection Report



Figure 11

Boorley Gardens, Development Tree Protection Report



Figure 12

Boorley Gardens, Development Tree Protection Report



Figure 13



Figure 14

Boorley Gardens, Development Tree Protection Report



Figure 15

Boorley Gardens, Development Tree Protection Report



Figure 16

Boorley Gardens, Development Tree Protection Report



Figure 17

Boorley Gardens, Development Tree Protection Report



Figure 18

Boorley Gardens, Development Tree Protection Report



Figure 19

Boorley Gardens, Development Tree Protection Report



Figure 20

Boorley Gardens, Development Tree Protection Report



Figure 21

Boorley Gardens, Development Tree Protection Report



Figure 22

Boorley Gardens, Development Tree Protection Report



Figure 23

Boorley Gardens, Development Tree Protection Report



Figure 24

Boorley Gardens, Development Tree Protection Report



Figure 25

Boorley Gardens, Development Tree Protection Report



Figure 26

Boorley Gardens, Development Tree Protection Report



Figure 27

Boorley Gardens, Development Tree Protection Report



Figure 28

Boorley Gardens, Development Tree Protection Report



Figure 29

Boorley Gardens, Development Tree Protection Report



Figure 30

Boorley Gardens, Development Tree Protection Report



Figure 31

Boorley Gardens, Development Tree Protection Report



Figure 32

Boorley Gardens, Development Tree Protection Report



Figure 33

Boorley Gardens, Development Tree Protection Report



Figure 34



Figure 35!

Boorley Gardens, Development Tree Protection Report



Figure 35!

Boorley Gardens, Development Tree Protection Report



Figure 36

Boorley Gardens, Development Tree Protection Report



Figure 37

Boorley Gardens, Development Tree Protection Report



Figure 38



Figure 39

Boorley Gardens, Development Tree Protection Report



Figure 40

Boorley Gardens, Development Tree Protection Report



Figure 41!

Boorley Gardens, Development Tree Protection Report



Figure 42

Boorley Gardens, Development Tree Protection Report



Figure 43

Boorley Gardens, Development Tree Protection Report



Figure 44



Figure 45