

Title:	Tree Protection Report
Site Address:	Boorley Gardens; Off Winchester Road, Botley SO32 2UA
Month of Inspection:	April 2026
Inspection Carried out by:	Jackson Rowe
Version:	1



Boorley Gardens Development - Tree Protection Report – 15.04.2026



Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 1



Figure 2

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 3

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 4

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 5

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 6

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 7

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 8

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 9



Figure 10



Figure 11



Figure 12



Figure 13

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 14



Figure 15



Figure 16

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 17



Figure 18

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 19



Figure 20



Figure 21



Figure 22

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 23

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 24

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 25



Figure 26

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 27

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 28

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 29



Figure 30



Figure 31

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 32




Figure 33



Figure 34

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 35



Figure 36



Figure 37



Figure 38

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 39



Figure 40



Figure 41



Figure 42

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 43



Figure 44



Figure 45

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 46

Boorley Gardens Development - Tree Protection Report – 15.04.2026

Photo removed as fencing is within the school site and is no longer under Miller/Bellway control

Figure 47

Boorley Gardens Development - Tree Protection Report – 15.04.2026

Photo removed as fencing is within the school site and is no longer under Miller/Bellway control

Figure 48

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 49 – this area is within the Care Home land under control of others and no longer needs to be photographed for the Miller/Bellway report

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 50 - this area is within the Care Home land under control of others and no longer needs to be photographed for the Miller/Bellway report

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 51 - this area is within the Care Home land under control of others and no longer needs to be photographed for the Miller/Bellway report

Boorley Gardens Development - Tree Protection Report – 15.04.2026



Figure 52 - this area is within the Care Home land under control of others and no longer needs to be photographed for the Miller/Bellway report

