


Title:	Tree Protection Report
Site Address:	Boorley Gardens; Off Winchester Road, Botley SO32 2UA
Month of Inspection:	June 2026
Inspection Carried out by:	Jackson Rowe
Version:	1



Boorley Gardens Development - Tree Protection Report – June 2026



e

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 1

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 2

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 3

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 4

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 5

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 6

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 7

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 8

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 9

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 10

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 11



Figure 12

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 13

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 14

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 15

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 16

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 17

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 18

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 19

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 20

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 21

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 22

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 23

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 24

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 25, fallen branch has since been removed

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 26

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 27

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 28

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 29

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 30

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 31



Figure 32

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 33

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 34



Figure 35

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 36

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 37



Figure 38

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 39

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 40

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 41

Boorley Gardens Development - Tree Protection Report – June 2026




Figure 42




Figure 43

Boorley Gardens Development - Tree Protection Report – June 2026




Figure 44

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 45

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 46



Figure 47

Boorley Gardens Development - Tree Protection Report – June 2026



Figure 48

Boorley Gardens Development - Tree Protection Report – June 2026




Figure 49