

Appendix 2A - Ross Blakemore Proof of Evidence

Image 3: Trial Hole 2 - Annotated




Image 3: Trial Hole 2 tarmac layer and below this was a single layer of stone hardcore, the geotextile membrane is not visible in this photo because of the water.