

Appendix 1A - Ross Blakemore Proof of Evidence

Image 2: Trial Hole 1 - Annotated




Image 2: Trial Hole 1 – tarmac layer and below this was a single layer of stone hardcore, the geotextile membrane is visible in this photo just below the waterline.