
18 CROWSPORT
HAMBLE
S031 4HG



AERIAL SHOTS



FRONT DOOR



HALLWAY



HALLYWAY (CONTD.)



LIVING ROOM



LIVING ROOM (CONTD.)



DINING ROOM





KITCHEN





EN SUITE



MASTER BEDROOM



FITTED WARDROBES IN MASTER BEDROOM REMOVED DUE TO EXCESSIVE DAMP PROBLEMS



MASTER BEDROOM (CONTD.)



BEDROOM 2




BEDROOM 2 (CONTD.)



BEDROOM 3



UTILITY ROOM



OFFICE

