

Title: Tree Protection Report

Site Address: Boorley Gardens; Off Winchester Road, Botley SO32 2UA


Month of Inspection: September 2024

Inspection Carried out by: Ben Hewlett – Technical Trainee & Daryl Roberts – Technical Project Manager, Miller Homes

Version: 0.0



Boorley Gardens, Development Tree Protection Report



Boorley Gardens, Development Tree Protection Report



Figure 1



Figure 2

Boorley Gardens, Development Tree Protection Report




Figure 3




Figure 4

Boorley Gardens, Development Tree Protection Report



Figure 5



Figure 6

Boorley Gardens, Development Tree Protection Report



Figure 7



Figure 8

Boorley Gardens, Development Tree Protection Report



Figure 9



Figure 10

Boorley Gardens, Development Tree Protection Report



Figure 11



Figure 12

Boorley Gardens, Development Tree Protection Report



Figure 13



Figure 14

Boorley Gardens, Development Tree Protection Report



Figure 15



Figure 16 – No Tree Protection

Boorley Gardens, Development Tree Protection Report



Figure 17



Figure 18

Boorley Gardens, Development Tree Protection Report



Figure 19



Figure 20

Boorley Gardens, Development Tree Protection Report



Figure 21



Figure 22

Boorley Gardens, Development Tree Protection Report



Figure 23



Figure 24

Boorley Gardens, Development Tree Protection Report



Figure 25

No photo

Figure 26

Boorley Gardens, Development Tree Protection Report

No photo	No photo
Figure 27	Figure 28

Boorley Gardens, Development Tree Protection Report