

Title: Tree Protection Report

Site Address: Boorley Gardens; Off Winchester Road, Botley SO32 2UA


Month of Inspection: November 2024

Inspection Carried out by: Ben Hewlett – Technical Trainee, Miller Homes

Version: 0.0



Boorley Gardens, Development Tree Protection Report



Boorley Gardens, Development Tree Protection Report




Figure 1




Figure 2

Boorley Gardens, Development Tree Protection Report



Figure 3



Figure 4

Boorley Gardens, Development Tree Protection Report



Figure 5



Figure 6

Boorley Gardens, Development Tree Protection Report



Figure 7



Figure 8

Boorley Gardens, Development Tree Protection Report



Figure 9



Figure 10

Boorley Gardens, Development Tree Protection Report



Figure 11



Figure 12

Boorley Gardens, Development Tree Protection Report



Figure 13 & 14



Figure 15

Boorley Gardens, Development Tree Protection Report



Figure 16 – No Tree Protection



Figure 17

Boorley Gardens, Development Tree Protection Report



Figure 18



Figure 19

Boorley Gardens, Development Tree Protection Report



Figure 20



Figure 21

Boorley Gardens, Development Tree Protection Report



Figure 22



Figure 23

Boorley Gardens, Development Tree Protection Report



Figure 24

No photo

Figure 25

Boorley Gardens, Development Tree Protection Report

No photo	No photo
Figure 26	Figure 27

Boorley Gardens, Development Tree Protection Report

No photo	No photo
Figure 28	Figure 29

Boorley Gardens, Development Tree Protection Report