

## Land at Grange Road, Netley - Condition 14 of O/16/78014



**Image 1:** Trees along western boundary protected by heras fencing




**Image 2:** Trees along northern boundary



**Image 3:** Trees along eastern boundary



**Image 4:** Trees in northwest corner



**Image 5:** Surfacing being finished in southwest corner



**Image 6:** Tree protection on Grange Road boundary



**Image 7:** Finished surfacing next to T5



**Image 8:** Finished surfacing next to T8