

Land at Grange Road, Netley - Condition 14 of O/16/78014



Image 1: Tree protection notice on fencing.



Image 2: T22 failed and collapsed over boundary fencing.



Image 3: Tree protection barriers along roadside trees G2, and H3



Image 4: Tree protection barriers along roadside trees H3, T4 and T5



Image 5: Tree protection barriers along western boundary adjacent to trees H10—T17



Image 6: Tree protection barriers adjacent to T8