

Title: Tree Protection Report

Site Address: Boorley Gardens; Off Winchester Road, Botley SO32 2UA


Month of Inspection: July 2025

Inspection Carried out by: Ben Hewlett – Technical Trainee, Miller Homes

Version: 0.0



Boorley Gardens, Development Tree Protection Report



Boorley Gardens, Development Tree Protection Report



Figure 1



Figure 2

Boorley Gardens, Development Tree Protection Report



Figure 3



Figure 4

Boorley Gardens, Development Tree Protection Report



Figure 5



Figure 6

Boorley Gardens, Development Tree Protection Report



Figure 7



Figure 8

Boorley Gardens, Development Tree Protection Report



Figure 9



Figure 10

Boorley Gardens, Development Tree Protection Report



Figure 11



Figure 12 & 13

Boorley Gardens, Development Tree Protection Report



Figure 14



Figure 15

Boorley Gardens, Development Tree Protection Report



Figure 16



Figure 17

Boorley Gardens, Development Tree Protection Report




Figure 18



Figure 19

Boorley Gardens, Development Tree Protection Report



Figure 20



Figure 21

Boorley Gardens, Development Tree Protection Report

Figure 22	Figure 23

Boorley Gardens, Development Tree Protection Report

No photo	No photo
Figure 24	Figure 25

Boorley Gardens, Development Tree Protection Report

No photo	No photo
Figure 26	Figure 27

Boorley Gardens, Development Tree Protection Report

No photo	No photo
Figure 28	Figure 29

Boorley Gardens, Development Tree Protection Report