

Title: Tree Protection Report

Site Address: Boorley Gardens; Off Winchester Road, Botley SO32 2UA

Month of Inspection: September 2025


Inspection Carried out by: Jonathan Clemenson – Technical Trainee, Miller Homes

/ Ben Hewlett – Technical Trainee, Miller Homes

Version: 0.0



Boorley Gardens, Development Tree Protection Report



Boorley Gardens, Development Tree Protection Report



Figure 1



Figure 2

Boorley Gardens, Development Tree Protection Report



Figure 3



Figure 4

Boorley Gardens, Development Tree Protection Report



Figure 5



Figure 6

Boorley Gardens, Development Tree Protection Report



Figure 7



Figure 8

Boorley Gardens, Development Tree Protection Report



Figure 9



Figure 10

Boorley Gardens, Development Tree Protection Report



Figure 11



Figure 12 & 13

Boorley Gardens, Development Tree Protection Report



Figure 14



Figure 15

Boorley Gardens, Development Tree Protection Report



Figure 16



Figure 17 &18

Boorley Gardens, Development Tree Protection Report



Figure 19



Figure 20

Boorley Gardens, Development Tree Protection Report



Figure 21

Figure 21

Boorley Gardens, Development Tree Protection Report

Figure 22	Figure 23

Boorley Gardens, Development Tree Protection Report

No photo	No photo
Figure 24	Figure 25

Boorley Gardens, Development Tree Protection Report

No photo	No photo
Figure 26	Figure 27

Boorley Gardens, Development Tree Protection Report

No photo	No photo
Figure 28	Figure 29

Boorley Gardens, Development Tree Protection Report